Index

A

Acidity
  Comparison of pH and acidity, 19
  Definition, 19
  Determination, 15–17, 19–24
  Uncertainty in measurement, 16, 19
Aluminum
  Concentration in rain, 25
  Effect on charge balance, 25
Analysis
  Acidity, 15–17, 19–24
  Ions by ion chromatography, 29–40
  pH, 15
  Reanalysis criteria, 79, 80

B

Blind samples
  Use in quality assurance, 80

C

Campbell, Sally, editor, 1–2, 91–96
Canadian Network for Sampling Precipitation
  Network description, 85–88
  Siting criteria, 85
Carbon dioxide in determination of acidity, 21
Charge (ion) balance
  Comparison or measured and computed pH values, 19, 78
  Computation of pH by, 25, 77, 78
  Uncertainty in, 26, 77, 78
Chloride determination by ion chromatography, 29–40
Cloud condensation nuclei characteristics, 7
Cloud formation mechanisms, 7
Collectors, *see* precipitation collectors
Conductance
  Computation, 77, 78
  Use in data checking, 78, 79

D

Data checking computational procedures, 77–80
Data comparability
  Definition, 63
  Importance of quality control, 65, 66
Data reporting for data comparability, 65–67
Deposition rate
  Relation to rainfall rate and event type, 55, 56
  Within event variability, 51
Detection limit
  Definition, 75
  Values for: NADP, 75

F

Field blanks use in quality assurance, 70
Field measurements comparison with laboratory, 80, 81
Fitchett, Arthur W., 29–40

Copyright© 1983 by ASTM International www.astm.org

H

Hayes, Janet V., 50–60
Hydrogen sulfide determination by ratiometric colorimetry, 41–49

I

Ion balance, *see* charge balance
Ion chromatography
  Analysis of rain, 29–40
  Precision and accuracy, 37–39

J

Jansen, John J., 61–71

K

Kimbell, Charles L., 41–49
Kimbell, Chris L., 41–49
Koch, William F., 10–17

L

Landsberg, H. E., 3–9

M

Marinenko, George, 10–17
Monitoring
  Data comparability, 62–64
  Existing networks, 62, 63

N

National Atmospheric Deposition Program (NADP)
  Analysis protocol, 76
  Data checking procedures, 77–79
  Network description, 72–75
  Quality assurance, 77–82
  Reanalysis criteria, 80
  Sampling protocol, 73–75
  Sites, 74
Nitrate
  Determination by ion chromatography, 29–40
  Within-event variability, 51–56

P

Peden, Mark E., 72–83
pH
  Computation from charge balance, 25, 26, 77–79
  Data comparability, 64–66
  Definition, 11, 12
  Determination in rain, 15, 76
  Effect of added salt on reported pH, 14, 15
  Effect of stirring on reported pH, 13, 14
  Electrode variability, 12, 13
  Related to ammonia, 53, 54
  Related to drop size, 8
  Uncertainty in measurement, 15, 24, 25, 81, 82
  Within-event variability, 51–56
Phosphate determination by ion chromatography, 29–40
Precipitation chemistry
  Data comparability, 62–64
  NADP analysis protocol, 76
  Relationship to meteorology, 53
  Relationship to rainfall rate, 54
  Variability within events, 51, 52
Precipitation collectors
  CANSAP protocol, 87, 88
  NADP protocol, 73

Q

Quality assurance/quality control
  Acidity measurements, 19–24
  CANSAP procedures, 89
  Computer data checks, 77–80
  Diagnosis of analytical problems, 79
  Field blanks, 70

For data comparability, 65
NADP procedures, 77–82
pH measurements, 15, 77–82
Program design considerations, 87
Program elements, 69, 77–82
Responsibilities of data producer and data analyst, 65
Round robins, 81, 82
UAPSP procedures, 67–70
Use of outside auditors, 69, 80–82
Workshop on data comparability, 69, 70

R

Raindrop
Formation, 7
Size distribution, 7
Rainfall
Gages, comparison, 4–6
Geographical variability, 4, 5
Uncertainty in measurement, 4, 5
Ratiometric colorimetry for analysis of total sulfur, 41–49
Raynor, G. S., 50–60
Reference materials, artificial rainwater, 10, 11
Round robins for network quality assurance, 81, 82

S

Scavenging of atmospheric contaminants by rain and snow, 6, 7, 51–53
Effect of droplet size, 7, 8
Sequential sampling for determination of sources of acidity, 51
Snow gages, 5
Still, Malcolm E., 84–90
Storage of precipitation samples, NADP protocol, 76
Sulfate
Dependence on meteorological variables, 56
Deposition rate related to rainfall rate, 56
Determination by ion chromatography, 29–40
Determination by ratiometric colorimetry, 41–49
Within-event variability, 51–56
Sulfite
Determination by ion chromatography, 29–40
Determination by ratiometric colorimetry, 41–49

T

Trace metal constituents
Concentrations in rain, 25
Contribution to acidity, 25
Trajectory analysis for determination of source regions, 56–59
Trend analysis data comparability, 63–65
Tyree, Sheppard Y., Jr., 18–28

U

Utility Acid Precipitation Study Program
Network description, 67, 68
Quality assurance program, 69
Workshop on data comparability, 69, 70