

# Cleanup Criteria for Contaminated Soil and Groundwater

---

---

**1996 Edition**

**Anthony J. Buonicore, Editor**

ASTM Data Series: DS 64  
ASTM Publication Code Number (PCN):  
Hard Cover: 28-064096-65  
Soft Cover: 28-064196-65



100 Barr Harbor Drive • West Conshohocken, PA 19428-2959

# Contents

<b>Chapter 1: Cleanup Criteria for Contaminated Soil and Groundwater</b>	<b>1</b>
Table 1: Representative Limits of Detection	<b>5</b>
<b>Chapter 2: Risk-Based Cleanup Criteria</b>	<b>11</b>
Table 2: Potential Exposure Pathways for Human Receptors	<b>14</b>
Table 3: Toxicity Data	<b>16</b>
<b>Chapter 3: National Standards and Guidelines</b>	<b>21</b>
Table 4: Action Levels Under RCRA Corrective Action	<b>29</b>
Table 5: Residue Concentration Limits for Nonmetallic Constituents	<b>32</b>
Table 6: EPA Toxicity Characteristic Regulatory Levels	<b>35</b>
Table 7: Universal Treatment Standards	<b>36</b>
Table 8: EPA Current and Proposed Drinking Water Standards	<b>41</b>
Table 9: Superfund Proposed Soil Screening Levels (SSLs)	<b>44</b>
Table 9A: EPA Region IX Preliminary Remediation Goals (PRGs)	<b>49</b>
Table 10: EPA PCB Contaminated Soil Cleanup Policy	<b>71</b>
Table 10A: Example Tier 1 Risk-Based Screening Levels (RBSLs) in ASTM E 1739-95 (at $10^{-6}$ Cancer Risk)	<b>72</b>
<b>Chapter 4: Background Concentrations</b>	<b>75</b>
Table 11: Background Concentrations of Elements in Soils	<b>77</b>
<b>Chapter 5: Cleanup Criteria Outside the United States</b>	<b>79</b>
Table 12: Contaminant Indicator Criteria Used by The Netherlands	<b>81</b>
Table 13: Maximum Allowable Concentrations (MAC) and Tentative Allowable Concentrations (TAC) of Contaminants in Soil in the Soviet Union (1984)	<b>85</b>
Table 14: Alberta Suggested Cleanup Guidelines for Inorganics in Soils	<b>88</b>
Table 15: Ontario Cleanup Guidelines for Soils	<b>89</b>
Table 16: Quebec Groundwater and Soil Contamination Indicators	<b>91</b>
Table 17: Tentative "Trigger Concentrations" for Selected Inorganics in the United Kingdom	<b>96</b>
Table 18: Reference Thresholds for Soil Pollutants in France	<b>98</b>
<b>Chapter 6: State Cleanup Standards and Guidelines</b>	<b>101</b>
Alabama	<b>103</b>
Alaska	<b>104</b>
Arizona	<b>107</b>
Arkansas	<b>123</b>
California	<b>124</b>
Colorado	<b>127</b>
Connecticut	<b>130</b>
Delaware	<b>138</b>
District of Columbia	<b>139</b>
Florida	<b>140</b>
Georgia	<b>142</b>
Hawaii	<b>169</b>
Idaho	<b>171</b>

Illinois	172
Indiana	175
Iowa	182
Kansas	183
Kentucky	189
Louisiana	191
Maine	192
Maryland	193
Massachusetts	194
Michigan	205
Minnesota	227
Mississippi	232
Missouri	233
Montana	238
Nebraska	239
Nevada	241
New Hampshire	242
New Jersey	244
New Mexico	250
New York	252
North Carolina	257
North Dakota	260
Ohio	261
Oklahoma	262
Oregon	264
Pennsylvania	270
Rhode Island	282
South Carolina	285
South Dakota	287
Tennessee	290
Texas	291
Utah	301
Vermont	302
Virginia	305
Washington	307
West Virginia	309
Wisconsin	311
Wyoming	315
<b>Appendix A: Chemical Names, CAS Numbers, Synonyms</b>	<b>321</b>
<b>Appendix B: Hazardous Substances List (RCRA, CERCLA, SARA)</b>	<b>397</b>
<b>Appendix C: State Agency Addresses</b>	<b>421</b>
<b>Appendix D: User's Guide to DS 64 Search Software</b>	<b>427</b>
Introduction	429
Getting Started	429
Tutorial	430
Trouble Shooting	437
Technical Support	437