

## SUBJECT INDEX TO 1963 REFERENCES

## 1. GENERAL (NO SPECIFIC MATERIAL)

- 1.1 Basic research, nature of fatigue:
  - 1.1.4 Correlations, mechanical properties: A-7
  - 1.1.4.3 Tensile and impact: A-42
  - 1.1.5 Deformation and fracture mechanisms: D-7, D-8
- 1.3 Geometric factors:
  - 1.3.1 Size: A-32, A-61
- 1.4 Surface factors:
  - 1.4.5 Surface hardening, cold work: A-22
- 1.5 Other influencing variables:
  - 1.5.1 Speed: A-41
  - 1.5.4 Type of loading: B-4, D-6
- 1.6 Environmental factors: A-10, B-2
  - 1.6.1 Temperature: A-41
  - 1.6.3 Fretting: A-8
  - 1.6.5 Thermal cycling, strain cycling, low cycle fatigue: A-57, D-2
  - 1.6.7 Acoustic: A-3, A-20, A-51, A-60
- 1.7 Fatigue damage and measurement:
  - 1.7.2 Crack propagation: A-16, A-57, A-59, A-61, B-4
  - 1.7.3 Cumulative damage: A-25, A-32, A-40, A-53, D-1
  - 1.7.3.5 Step, sequential, spectrum tests: A-24, A-46, A-53
- 1.8 Test methods and machines: A-18, A-33, A-34, A-45, A-56, D-2, D-3
  - 1.8.1 Fatigue machines: A-50
  - 1.8.2 Control apparatus: A-50
  - 1.8.3 Statistical approaches: A-1, A-7, A-19, D-4
- 1.10 Fatigue properties of structures and machines:
  - 1.10.1 Joints and joining methods:
    - 1.10.1.2 Bolts and bolted joints: A-58
    - 1.10.1.3 Spot welds and other fusion welded joints: A-32
  - 1.10.2 Other components of machines and structures: A-14
  - 1.10.3 Large scale structural and machine members: A-1, A-3, A-5, A-19, A-20, A-21, A-22, A-24, A-25, A-39, A-43, A-47, D-3
- 1.12 Theoretical discussions, general review:
  - 1.12.1 Theoretical treatments, fatigue and related effects: A-48
  - 1.12.2 Historical summaries: A-10
  - 1.12.4 Books: A-2, A-4, A-6
- 2.5 Other influencing variables:
  - 2.5.2 Mean stress, alternating stress: A-9
- 2.6 Environmental factors:
  - 2.6.1 Temperature: B-3
  - 2.6.1.2 Low: A-17
  - 2.6.5 Thermal cycling, strain cycling, low cycle fatigue: A-13, A-62
- 2.7 Fatigue damage and measurement:
  - 2.7.2 Crack propagation: A-13
  - 2.7.3 Cumulative damage: A-23, B-3
  - 2.7.3.1 Prior stress or strain history: A-11
- 2.8 Test methods and machines:
  - 2.8.3 Statistical approaches: D-5
- 2.10 Fatigue properties of structures and machines:
  - 2.10.1 Joints and joining methods:
    - 2.10.1.2 Bolts and bolted joints: A-44
    - 2.10.1.3 Spot welds and other fusion welded joints: A-17
- 2.12 Theoretical discussions, general review:
  - 2.12.1 Theoretical treatments, fatigue and related effects: A-48

## 4. ALUMINUM ALLOYS

- 4.1 Basic research, nature of fatigue: A-28
  - 4.1.5 Deformation and fracture mechanisms: A-28
- 4.2 Composition and processing variables: C-1
  - 4.2.2 Microstructure: C-2
  - 4.2.3 Melting, molding, and casting techniques: B-5
- 4.3 Geometric factors:
  - 4.3.4 Stress concentrations: A-26, B-5
- 4.5 Other influencing variables:
  - 4.5.4 Type of loading: A-55
- 4.6 Environmental factors: A-30
  - 4.6.1 Temperature: B-3
  - 4.6.1.2 Low: A-57
  - 4.6.3 Fretting: A-26
  - 4.6.5 Thermal cycling, strain cycling, low cycle fatigue: A-62
  - 4.6.6 Humidity: A-15
  - 4.6.8 Vacuum: A-30
- 4.7 Fatigue damage and measurement:
  - 4.7.1 Detection of damage: A-27
  - 4.7.2 Crack propagation: B-6, C-2
  - 4.7.3 Cumulative damage: A-23, B-3
  - 4.7.3.1 Prior stress or strain history: A-11
  - 4.7.3.5 Step, sequential, spectrum tests: A-45, A-55
- 4.8 Test methods and machines: A-18, A-27
- 4.10 Fatigue properties of structures and machines:
  - 4.10.1 Joints and joining methods:
    - 4.10.1.1 Rivets and riveted joints: C-1
    - 4.10.1.2 Bolts and bolted joints: A-44
    - 4.10.1.3 Spot welds and other fusion welded joints: B-1
  - 4.10.3 Large scale structural and machine members: A-12

## 2. IRON AND STEEL

- 2.1 Basic research, nature of fatigue: C-3
  - 2.1.4 Correlations, mechanical properties: A-38
  - 2.1.4.1 Anelasticity: A-37
- 2.2 Composition and processing variables:
  - 2.2.2 Microstructure:
    - 2.2.2.1 Grain size or particle size: C-3
- 2.3 Geometric factors:
  - 2.3.1 Size: A-38
  - 2.3.4 Stress concentrations: A-9

## 4.12 Theoretical discussions, general reviews:

4.12.2 Historical summaries: A-33

## 5. COPPER ALLOYS

## 5.1 Basic research, nature of fatigue: A-29

5.1.5 Deformation and fracture mechanisms: A-49

## 5.2 Composition and processing variables:

5.2.1 Composition:

5.2.1.1 Alloying elements: A-29

## 7. TITANIUM ALLOYS

## 7.5 Other influencing variables:

7.5.1 Speed: A-35

7.5.4 Type of loading: A-35

## 7.6 Environmental factors:

7.6.1 Temperature:

7.6.1.1 High: A-35

## 7.7 Fatigue damage and measurement:

7.7.3 Cumulative damage:

7.7.3.1 Prior stress or strain history: A-11

## 10. CERAMIC MATERIALS

## 10.6 Environmental factors:

10.6.3 Fretting: A-31