

SUBJECT INDEX

1. GENERAL (NO SPECIFIC MATERIAL)
 - 1.1 Basic Research, Nature of Fatigue: A-57, A-420, A-423, A-434, A-521, B-19, B-38, B-137, B-147, B-423
 - 1.1.1 Experimental Materials: B-298
 - 1.1.2 Single and Large Crystals: A-22
 - 1.1.3 Correlations, Physical Properties: A-32, A-524, A-542, D-130, D-158
 - 1.1.3.2 Thermal Expansion: A-118
 - 1.1.4 Correlations, Mechanical Properties: A-34, A-390, C-124, C-222
 - 1.1.4.1 Anelasticity: A-153, A-157, A-159, D-58
 - 1.1.4.2 Damping: A-103, A-168, A-214, A-257, A-420, A-465, A-470, A-489, A-490, A-501, A-507, A-511, B-464, D-152, E-25
 - 1.1.4.3 Tensile and Impact: B-198, C-43, C-241, C-266, D-52
 - 1.1.4.4 Creep: A-364, A-447, A-493, B-178, B-305
 - 1.1.5 Deformation and Fracture Mechanisms: A-118, A-163, A-184, A-257, A-298, A-364, A-418, A-492, A-493, A-505, A-521, A-524, B-133, B-198, B-262, B-330, B-331, B-342, B-344, B-352, B-405, B-419, B-438, B-460, C-50, C-58, C-62, C-66, C-69, D-61, D-140, D-158
 - 1.2 Composition and Processing Variables: B-150, B-212
 - 1.2.2 Composition:
 - 1.2.2.1 Grain Size or Particle Size: A-424
 - 1.2.2.3 Anisotropy: A-548
 - 1.2.3 Melting, Molding, and Casting Techniques: A-408
 - 1.2.4 Primary and Secondary Fabrication: B-319
 - 1.2.5 Defects: A-548, B-226, B-324
 - 1.2.6 Heat Treatment (excluding surface hardening): A-65, A-420, B-142, C-1, C-126, C-143, C-187, C-227
 - 1.2.7 Other Factors: B-126
 - 1.3 Geometric Factors: A-127, B-150
 - 1.3.1 Size: A-279, A-342, B-126, B-226, C-57, C-112, C-171, C-186
 - 1.3.2 Shape: A-311, B-114, B-126, C-112, C-171, C-252, E-4
 - 1.3.3 Stress Gradient: A-412, B-121, B-215, C-70, D-35
 - 1.3.4 Stress Concentrations: A-49, A-105, A-116, A-125, A-182, A-264, A-408, A-420, A-447, A-548, B-29, B-46, B-56, B-62, B-96, B-114, B-121, B-127, B-132, B-133, B-139, B-142, B-149, B-312, B-341, C-95, C-144, C-186, C-241, C-251, C-266, C-267, C-272, E-4
 - 1.4 Surface Factors: A-65, A-349, A-420, B-77, B-150, C-1, C-10
 - 1.4.1 Machining Techniques: B-332, B-428
 - 1.4.2 Polishing Techniques: B-16
 - 1.4.3 Surface Finish: A-548, B-96, B-132, B-154, B-333, C-70
 - 1.4.4 Scratch Direction: A-126
 - 1.4.5 Surface Hardening, Cold Work: A-126, A-260, A-548, B-185, B-192, B-432, B-446, C-251
 - 1.4.6 Surface Hardening, Heat Treatment: C-227
 - 1.4.7 Residual Stresses: A-126, A-278, A-516, A-548, B-109, B-192, B-212, B-215, B-432, B-446, C-227, C-251, D-75
 - 1.4.8 Surface Coatings: C-126, D-106
 - 1.4.8.1 Electroplated: A-278
 - 1.4.9 Other Surface Factors: B-165, B-332, C-49, C-145
 - 1.5 Other Influencing Variables: B-150
 - 1.5.1 Speed: A-255, A-289, B-227, B-313, B-321, B-345, C-136
 - 1.5.2 Mean Stress, Alternating Stress: A-105, A-168, A-289, A-522, A-548, B-109, B-127, B-212, C-35, D-58
 - 1.5.3 Combined Stress: A-22, A-58, A-77, A-112, A-186, A-235, A-265, A-493, A-503, A-522, B-179, B-190, B-207, B-212
 - 1.5.4 Type of Loading: A-143, A-172, A-283, A-505, B-179, B-195, B-220, B-239, B-308, C-273, D-45, D-101, D-128, D-141
 - 1.6 Environmental Factors: A-334, A-420, B-150, C-19
 - 1.6.1 Temperature: A-157, A-302, A-315, A-548, B-289, B-345, B-401
 - 1.6.1.1 High: A-38, A-95, A-349, A-364, A-447, A-456, A-467, A-488, A-493, B-469, C-233, D-71, D-93, D-95, D-125
 - 1.6.2 Corrosion and Chemical Attack: A-92, A-135, A-548, B-128, B-144, B-235, B-311, B-347, C-49, D-95, D-139, D-141, E-19, E-53
 - 1.6.3 Fretting: A-135, B-33, B-128, B-204, B-255, B-353, B-405, B-472
 - 1.6.5 Thermal Cycling, Strain Cycling, Low Cycle Fatigue: A-95, A-239, A-352, A-353, A-354, A-364, A-399, A-418, A-429, A-492, A-493, A-503, B-100, B-133, B-188, B-243, B-440
 - 1.6.7 Acoustic: A-400, A-414, A-415, A-420, A-426, A-432, A-439, A-457, A-459, A-465, A-470, A-489, A-490, A-501, A-507, A-511, A-512, A-513, A-525, A-547, A-552, A-556, B-466, C-233
 - 1.7 Fatigue Damage and Measurement: A-57, A-92, A-511, A-522, A-542, B-150, B-165, B-212, B-220, C-29, C-190, D-130, E-39
 - 1.7.1 Detection of Damage: A-21, A-22, A-198, A-306, A-412, A-505, B-296, B-362, B-405, C-49, C-84, C-92, C-266, E-25, E-32
 - 1.7.1.1 Prior to Cracking: A-424, B-75, B-105, B-460, D-61
 - 1.7.1.2 After Cracking: A-47, A-138, B-105, B-139, B-308, B-460, D-61
 - 1.7.2 Crack Propagation: A-21, A-22, A-134, A-342, A-360, A-412, A-505, B-139, B-162, B-288, B-299, B-324, B-344, B-397, B-405, C-201
 - 1.7.3 Cumulative Damage: A-97, A-116, A-145, A-150, A-186, A-198, A-217, A-238, A-446, A-494, A-519, B-63, B-89, B-156, B-157, B-312, B-387, C-82, C-142, C-210, C-255, C-268
 - 1.7.3.1 Prior Stress or Strain History: A-153, A-353, A-354, B-55, B-160, B-464
 - 1.7.3.2 Rest Periods: A-548
 - 1.7.3.3 Understressing, Overstressing: B-109
 - 1.7.3.5 Step, Sequential, Spectrum Tests: A-98, A-121, A-246, A-422, A-435, A-438, A-475, A-482, A-483, B-143, B-144, B-163, B-216, C-52, C-229, C-237, C-240, D-121

- 1.8 Test Methods and Machines: A-125, A-143, A-299, A-334, A-412, A-453, B-24, B-150, B-252, B-253, B-254, B-258, B-281, B-375, B-388, B-408, B-411, C-111, C-198, C-205, C-274, D-42, D-45, D-46, D-60, D-104, D-124
 - 1.8.1 Fatigue Machines: A-46, A-54, A-55, A-74, A-98, A-101, A-158, A-159, A-163, A-188, A-203, A-214, A-224, A-231, A-237, A-244, A-300, A-301, A-308, A-320, A-400, A-406, A-440, A-453, A-457, A-474, A-488, A-512, A-525, A-541, A-560, A-562, B-30, B-69, B-72, B-99, B-178, B-195, B-227, B-246, B-247, B-251, B-263, B-359, B-361, B-376, B-387, B-401, B-403, B-433, B-466, B-469, C-19, C-75, C-138, C-209, C-218, C-255, C-262, C-263, C-273, D-1, D-7, D-20, D-32, D-56, D-59, D-71, D-78, D-96, D-97, E-2, E-15, E-49
 - 1.8.2 Control Apparatus: A-159, A-188, A-214, A-244, A-315, A-400, A-457, A-488, A-512, A-525, A-541, A-560, A-562, B-99, B-276, B-315, B-387, B-403, B-433, B-466, B-469, C-184, D-96, E-49
 - 1.8.3 Statistical Approaches: A-46, A-81, A-340, B-40, B-88, B-325, C-2, C-8, C-208, C-242, D-22
 - 1.8.3.1 Design of Experiments: A-475, A-481, A-551, A-552, B-63, B-267, B-468, C-38, C-73, C-233
 - 1.8.3.2 Analysis: A-56, A-120, A-190, A-191, A-194, A-246, A-314, A-401, A-424, A-481, A-483, A-551, A-552, B-17, B-27, B-44, B-308, B-378, B-406, B-468, C-7, C-21, C-28, C-29, C-52, C-54, C-63, C-81, C-226, C-248, C-266, D-72
 - 1.8.4 Programming of Tests: A-237, B-144, C-38, C-81, C-273
- 1.9 Engineering Problems and Design: A-92, A-95, A-97, A-125, A-135, A-161, A-174, A-238, B-2, B-10, B-100, B-113, B-124, B-126, B-127, B-130, B-142, B-150, B-177, B-212, B-230, B-270, B-355, B-356, B-357, B-367, C-4, C-83, C-169, C-199
 - 1.9.1 Service Failures: A-144, A-256, A-288, A-405, B-102, B-114, B-128, B-216, B-233, B-248, B-261, B-262, B-408, B-478, C-126, D-44, D-157
 - 1.9.2 Empirical Reduction of Fatigue Information to Formulas: A-24, A-112, A-194, A-364, A-438, A-453, A-488, A-493, A-494, A-522, B-17, B-56
 - 1.9.3 Application of Fatigue Data in Design: A-88, A-116, A-121, A-123, A-157, A-182, A-183, A-186, A-191, A-237, A-239, A-240, A-254, A-264, A-265, A-272, A-295, A-364, A-371, A-401, A-402, A-405, A-408, A-414, A-417, A-419, A-438, A-448, A-474, A-475, A-481, A-493, A-494, A-516, A-529, A-538, A-453, B-47, B-106, B-144, B-149, B-192, B-212, B-216, B-233, B-238, B-280, B-305, B-311, B-325, B-425, C-18, C-52, C-128, C-190, C-233, C-251, C-252, C-255, C-268, D-43
 - 1.9.4 Stress-Range Diagrams: A-417, A-529
- 1.10 Fatigue Properties of Structures and Machines: A-123, A-150, B-143, B-154, B-212, B-387
 - 1.10.1 Joints and Joining Methods: B-57, B-161, C-251
 - 1.10.1.1 Rivets and Riveted Joints: A-448
 - 1.10.1.2 Bolts and Bolted Joints: A-448, B-22, B-33, B-405, B-414, C-23, D-27
 - 1.10.1.3 Spot Welds and Other Fusion Welded Joints: A-36, A-75, A-448, A-474, B-309, B-453, C-24, C-93, C-128, C-206, D-33, D-35, D-62
 - 1.10.1.4 Adhesives and Adhesive Joints: A-489, C-39, C-120, C-274, D-95
 - 1.10.2 Other Components of Machines and Structures: A-144, A-256, A-272, A-290, A-302, A-422, A-440, A-482, A-512, A-538, A-562, B-141, B-161, B-246, B-336, B-408, C-71, C-125, C-126, C-139, C-145, C-241, C-246, C-251, C-272, D-127, D-152
 - 1.10.2.1 Gears: B-187, D-88
 - 1.10.2.2 Bearings: A-92, A-406, B-187, B-234, B-277
 - 1.10.3 Large Scale Structural and Machine Members: A-37, A-41, A-116, A-143, A-145, A-172, A-174, A-183, A-198, A-254, A-277, A-288, A-291, A-295, A-300, A-308, A-364, A-369, A-400, A-404, A-414, A-426, A-432, A-435, A-438, A-439, A-459, A-465, A-470, A-474, A-475, A-482, A-483, A-494, A-507, A-511, A-513, A-541, A-547, A-560, B-84, B-102, B-113, B-144, B-163, B-187, B-200, B-233, B-238, B-254, B-263, B-270, B-380, B-397, B-466, B-471, C-96, C-190, C-219, C-222, C-233, C-255, C-259, C-260, C-263, C-268, C-273, D-147
- 1.11 Fatigue Properties of Materials (data-generating studies): B-219, C-84, E-49
- 1.12 Theoretical Discussions, General Reviews: A-7, A-28, A-47, A-66, A-69, A-145, A-166, A-184, A-264, A-265, A-337, A-340, A-360, A-423, A-446, A-467, B-4, B-7, B-9, B-12, B-14, B-26, B-29, B-68, B-78, B-80, B-81, B-83, B-85, B-86, B-133, B-137, B-147, B-151, B-162, B-163, B-168, B-177, B-184, B-221, B-230, B-245, B-259, B-305, B-319, B-325, B-330, B-344, B-368, B-377, B-402, B-419, B-422, B-423, C-2, C-43, C-111, C-112, C-157, C-190, C-196, C-199, C-236, D-14, D-15, D-16, D-21, D-22, D-44, D-46, D-143, E-6, E-13
 - 1.12.1 Theoretical Treatments, Fatigue and Related Effects: A-38, A-57, A-97, A-112, A-116, A-118, A-134, A-149, A-160, A-313, A-342, A-390, A-399, A-404, A-415, A-420, A-424, A-434, A-483, A-519, A-556, A-560, A-562, B-46, B-75, B-102, B-121, B-194, B-207, B-243, B-396, C-44, C-98, C-99, C-160, D-48
 - 1.12.2 Historical Summaries: A-21, A-22, A-356, A-405, A-445, A-516, A-548, B-411, B-471, C-88, C-263, D-68, D-83
 - 1.12.3 Bibliographies: A-103, A-492, B-102, B-150
 - 1.12.4 Books: A-116, A-321, A-424, A-434, A-508, A-523, B-250, B-289, B-324, B-464, C-221

2. IRON AND STEEL

- 2.1 Basic Research, Nature of Fatigue: B-158, C-25
 - 2.1.1 Experimental Materials: A-500
 - 2.1.2 Single and Large Crystals: C-113, C-114, C-181
 - 2.1.3 Correlations, Physical Properties: A-557, E-16, E-23
 - 2.1.4 Correlations, Mechanical Properties: A-53, A-146, A-320, A-387, A-396, B-320, B-394, B-429, C-176, D-29, D-155
 - 2.1.4.1 Anelasticity: E-16, E-33
 - 2.1.4.2 Damping: A-226, C-225, E-33

- 2.1.4.3 Tensile and Impact: A-177, A-187, A-209, A-458, A-479, A-486, B-167, B-201, C-267, D-119
- 2.1.4.4 Creep: B-240
- 2.1.5 Deformation and Fracture Mechanisms: A-207, A-379, A-458, A-464, A-537, B-224, B-314, B-329, B-449, C-74, C-183, D-67, D-69, D-148, E-30
- 2.2 Composition and Processing Variables: A-4, A-29, A-318, B-138, B-394, B-434, D-26, D-99
 - 2.2.1 Composition: A-164, A-215, A-386, A-518, A-544
 - 2.2.1.1 Alloying Elements: A-87, A-99, A-128, A-146, A-393, A-421, A-500, A-543, B-103, B-211, B-473, C-3, D-52, D-89, D-134, D-151
 - 2.2.1.2 Interstitials: B-169, B-473
 - 2.2.1.3 Reinforcing, Laminating or Filler Materials: A-544
 - 2.2.2 Microstructure: A-316, A-386, A-396, A-464, A-543, A-544, B-91, B-224, B-431, C-163, C-257, D-85, E-55
 - 2.2.2.1 Grain Size or Particle Size: B-67, B-167, C-269
 - 2.2.2.2 Grain Orientation: D-144
 - 2.2.2.3 Anisotropy: A-26, A-114, A-187, B-115, C-167, D-92, D-103
 - 2.2.3 Melting, Molding, and Casting Techniques: A-18, A-178, A-297, A-431, A-518, B-41, B-167, E-42
 - 2.2.4 Primary and Secondary Fabrication: A-43, A-284, A-377, A-378, B-59, B-60, D-98
 - 2.2.4.2 Rolling: A-187, A-266, A-304, D-81, D-162
 - 2.2.5 Defects: A-236, A-268, B-237, B-455, C-127, C-146
 - 2.2.5.1 Inclusions: A-18, A-187, A-225, A-229, A-320, A-332, A-346, A-421, A-431, B-167, B-199, B-218, B-360, B-455, B-476, C-224, E-33
 - 2.2.5.2 Porosity: B-115, B-455, B-476
 - 2.2.6 Heat Treatment (excluding surface hardening): A-29, A-78, A-94, A-114, A-177, A-195, A-199, A-215, A-386, A-393, A-431, A-437, A-500, A-506, A-518, A-543, A-545, A-546, A-561, B-45, B-93, B-208, B-211, B-225, B-294, B-431, B-457, C-26, C-27, C-64, C-65, C-119, C-267, D-12, D-19, D-27, D-28, D-30, D-36, D-38, D-84, D-85, D-103, D-118, D-120, D-139, D-151, D-155, E-7, E-26
 - 2.2.7 Other Factors: A-96, A-331, A-407, B-93, B-104, B-374
- 2.3 Geometric Factors: A-4, A-107, B-125
 - 2.3.1 Size: A-215, A-325, A-561, B-67, B-70, B-412, C-33, C-130, C-257, D-103, D-114, D-144
 - 2.3.2 Shape: A-108, A-158, A-195, A-540, A-561, B-457, C-33, C-257, D-74, D-155
 - 2.3.3 Stress Gradient: A-29, C-132, C-247
 - 2.3.4 Stress Concentrations: A-87, A-90, A-107, A-108, A-162, A-171, A-179, A-195, A-215, A-226, A-310, A-332, A-374, A-379, A-386, A-387, A-393, A-425, A-449, A-486, A-506, A-561, B-35, B-67, B-120, B-134, B-140, B-208, B-211, B-218, B-240, B-241, B-292, B-435, B-442, B-457, C-18, C-33, C-91, C-224, C-247, C-257, C-258, C-267, D-132, D-133, D-150, D-159, E-15, E-20, E-24, E-26, E-31, E-37, E-46
- 2.4 Surface Factors: A-29, B-457, C-33, C-123, C-257, C-258
 - 2.4.1 Machining Techniques: A-346, A-377, A-378, A-468, A-555, B-28, C-197, D-70
 - 2.4.2 Polishing Techniques: C-197, E-43
 - 2.4.3 Surface Finish: A-107, A-276, A-286, A-287, A-386, A-395, A-413, A-502, B-116, B-333, C-64, C-203, D-4, D-77, E-56
 - 2.4.4 Scratch Direction: A-377, A-378
 - 2.4.5 Surface Hardening, Cold Work: A-5, A-20, A-180, A-205, A-215, A-243, A-305, A-333, A-377, A-394, A-437, A-469, A-491, A-535, A-545, A-555, B-116, B-117, B-118, B-225, B-236, B-265, B-363, B-371, B-417, B-451, C-116, C-147, C-197, D-37, D-73, D-111, D-131, D-155, D-159, E-28, E-38, E-43, E-55, E-56
 - 2.4.6 Surface Hardening, Heat Treatment: A-3, A-128, A-261, A-333, B-240, B-417, C-64, C-232, D-31, D-55, D-98, D-159, E-34
 - 2.4.6.1 Carburizing: A-437, C-90, C-235, D-73, D-137
 - 2.4.6.2 Nitriding: A-366, A-437, A-469, A-509, C-174, C-211, C-212, C-213, C-228, C-235, C-245, C-253, C-269, C-270
 - 2.4.7 Residual Stresses: A-233, A-284, A-287, A-346, A-377, A-464, A-468, A-491, A-495, A-496, B-164, B-180, B-237, B-322, B-338, B-412, B-451, C-9, C-26, C-27, C-232, D-10, D-81, D-82, D-155, D-162, E-28
 - 2.4.8 Surface Coatings: B-370
 - 2.4.8.1 Electroplated: A-2, A-62, A-63, A-263, A-305, A-437, A-469, A-491, A-545, A-555, B-13, B-50, B-51, B-90, B-264, B-338, B-350, B-371, B-424, C-253, C-271, D-29, D-111
 - 2.4.8.2 Other Coatings: A-468, B-201, B-249, B-340, C-64, C-253, C-254, D-133
 - 2.4.9 Other Surface Factors: A-178, A-554, B-191, B-205, B-208, B-236, C-211, C-212, C-213, D-47, D-77
- 2.5 Other Influencing Variables:
 - 2.5.1 Speed: A-29, A-236, B-186, B-286, C-100, D-49, E-50
 - 2.5.2 Mean Stress, Alternating Stress: A-94, A-425, A-430, A-441, A-496, B-115, B-116, B-129, B-203, B-240, B-292, B-435, D-28, D-86, E-51
 - 2.5.3 Combined Stress: A-10, A-48, A-430, A-544, B-122, B-129, B-182, B-197, B-205, E-48
 - 2.5.4 Type of Loading: A-26, A-94, A-177, A-178, A-187, A-322, A-323, A-324, A-544, A-561, B-122, B-195, B-201, C-261, D-57, D-132, E-36
- 2.6 Environmental Factors: A-107, A-344, C-33, E-43
 - 2.6.1 Temperature: A-442, C-33, C-166
 - 2.6.1.1 High: A-215, A-368, A-387, A-407, A-441, A-518, A-549, A-554, B-91, B-108, B-240, B-286, B-320, B-329, B-431, B-445, C-267, D-5, D-29, D-87, D-115, D-116, D-134, D-148, E-35
 - 2.6.1.2 Low: A-215, A-458, A-554, B-31, B-134, B-158, B-201, B-316, E-40
 - 2.6.2 Corrosion and Chemical Attack: A-442, B-1, B-3, B-91, B-104, B-120, B-146, B-153, B-174, B-191, B-320, C-33, C-253, C-261, D-9, D-18, D-19, D-66, D-123, D-131, E-9, E-21, E-50, E-51
 - 2.6.3 Fretting: A-266, A-284, A-357, A-530, B-164, B-366, C-11, C-158, C-172, C-200
 - 2.6.5 Thermal Cycling, Strain Cycling, Low Cycle Fatigue: A-90, A-108, A-253, A-537, B-70, B-117, B-202, B-434, C-32, D-49, D-76, D-87, D-148
 - 2.6.7 Acoustic: C-167
- 2.7 Fatigue Damage and Measurement: B-6, B-439, C-46
 - 2.7.1 Detection of Damage: A-21, A-226, A-413, A-476, B-140, D-108, E-45, E-46
 - 2.7.1.1 Prior to Cracking: B-449
 - 2.7.1.2 After Cracking: B-134, E-5, E-12
 - 2.7.2 Crack Propagation: A-21, A-168, A-333, A-339, A-476,

- A-485, A-561, B-70, B-287, B-290, B-291, B-292, B-431, B-435, C-60, C-123, C-182, E-38, E-47
- 2.7.3 Cumulative Damage: A-31, A-337, A-389, B-214, E-15
 - 2.7.3.1 Prior Stress or Strain History: A-215, A-338, A-479, A-561, B-272, B-442
 - 2.7.3.3 Understressing, Overstressing: A-27, A-215, B-145 B-323, C-48, D-40
 - 2.7.3.4 Coaxing: A-27
 - 2.7.3.5 Step, Sequential, Spectrum Tests: A-88, A-221, A-368, A-428, A-431, A-436, A-476, B-119, C-34, C-91, E-3
- 2.8 Test Methods and Machines: B-182, C-86, D-34, D-91, D-94, D-109, E-29
 - 2.8.1 Fatigue Machines: A-64, A-68, A-202, A-209, A-266, A-322, A-323, A-324, A-366, A-379, A-527, A-544, B-31, B-104, B-116, B-181, B-186, B-197, B-317, B-369, B-458, C-51, C-261, E-11
 - 2.8.2 Control Apparatus: A-527, B-110
 - 2.8.3 Statistical Approaches: A-45, A-80, A-266, C-188, E-14
 - 2.8.3.1 Design of Experiments: A-154, A-428, D-110
 - 2.8.3.2 Analysis: A-18, A-19, A-87, A-154, A-187, A-274, A-441, A-443, B-214, C-30, C-32, C-159, C-162
 - 2.8.4 Programming of Tests: A-527
- 2.9 Engineering Problems and Design: A-79, A-133, A-162, A-179, A-533, E-14
 - 2.9.1 Service Failures: A-20, A-44, A-52, A-76, A-78, A-80, A-100, A-216, A-294, A-359, B-8, B-93, B-101, B-112, B-120, B-174, B-237, B-242, B-249, B-295, B-348, B-389, B-476, C-6, C-194, C-216, C-217, D-90, E-10, E-39
 - 2.9.2 Empirical Reduction of Fatigue Information to Formulas: A-460, A-476, A-486, A-502, A-506, A-537, D-3
 - 2.9.3 Application of Fatigue Data in Design: A-107, A-270, A-460, A-463, A-466, A-530, B-106, B-390, C-215
- 2.10 Fatigue Properties of Structures and Machines: B-153, B-171,
 - 2.10.1 Joints and Joining Methods: B-181, B-182, D-4, D-117, E-1
 - 2.10.1.1 Rivets and Riveted Joints: A-282, A-450, C-71, D-142
 - 2.10.1.2 Bolts and Bolted Joints: A-11, A-310, A-450, B-390, D-27, D-153
 - 2.10.1.3 Spot Welds and Other Fusion Welded Joints: A-10, A-29, A-30, A-90, A-108, A-114, A-127, A-199, A-253, A-268, A-294, A-325, A-335, A-464, A-466, A-553, B-1, B-11, B-61, B-241, B-358, B-372, B-398, B-412, B-443, B-457, B-458, B-473, B-476, C-9, C-12, C-53, C-85, C-87, C-127, C-147, C-151, C-152, C-154, C-155, C-156, C-164, C-170, C-191, C-195, C-204, C-215, C-238, C-243, C-258, C-265, D-6, D-8, D-13, D-31, D-36, D-41, D-54, D-63, D-112, D-114, D-142, D-145, D-146, D-156, E-17
 - 2.10.2 Other Components of Machines and Structures: A-3, A-64, A-216, A-230, A-231, A-442, A-463, A-530, A-540, B-249, B-458, B-473, B-477, C-148, C-149, C-150, C-153, C-165, C-173, C-188, C-194, C-196, C-228, C-261, D-11, D-73, D-79, D-90, D-100, D-142, D-149, D-159, E-47
 - 2.10.2.1 Gears: A-398, A-413, A-460, A-527, A-535, B-101, B-382, C-158, C-270, D-55, D-102, D-110, D-132
 - 2.10.2.2 Bearings: A-96, A-154, A-201, A-208, A-218, A-219, A-220, A-441, A-502, A-533, A-549, A-554, B-110, B-125, B-241, B-277, B-369 B-384, C-59, C-158, D-39, D-92, D-120
 - 2.10.3 Large Scale Structural and Machine Members: A-99, A-100, A-248, A-251, A-268, A-331, A-359, B-23, B-31, B-107, B-125, C-5, C-127, C-146, C-238, D-47, D-151, D-161, E-29, E-37
- 2.11 Fatigue Properties of Materials (data-generating studies): A-18, A-25, A-87, A-110, A-225, A-261, A-271, A-275, A-282, B-18, B-41, B-138, B-316, B-318, B-329, C-14, C-79, C-117, C-132, D-26, D-89, D-122, E-20, E-49
- 2.12 Theoretical Discussions, General Reviews: A-31, A-261, A-266, B-70, B-171, B-314, C-130
 - 2.12.1 Theoretical Treatments, Fatigue and Related Effects: A-330, A-476, A-530, B-129, C-74, C-161, C-182, C-188, C-207
 - 2.12.2 Historical Summaries: A-468, A-517, B-455,
- 3. CORROSION- AND HEAT-RESISTANT MATERIALS
 - 3.1 Basic Research, Nature of Fatigue:
 - 3.1.4 Correlations, Mechanical Properties: A-252, A-343, A-347, B-420, D-154
 - 3.1.4.2 Damping: A-85, A-226, B-183
 - 3.1.4.3 Tensile and Impact: B-461
 - 3.1.4.4 Creep: A-71, A-241, A-382, A-383, A-416, A-546, B-310, B-459, E-54
 - 3.1.5 Deformation and Fracture Mechanisms: A-410, A-537, A-545, B-329, B-447, B-461
 - 3.2 Composition and Processing Variables:
 - 3.2.2 Microstructure: D-17
 - 3.2.2.1 Grain Size or Particle Size: A-376, A-536
 - 3.2.2.3 Forming: A-292
 - 3.2.6 Heat Treatment (excluding surface hardening): A-382, A-514
 - 3.3 Geometric Factors:
 - 3.3.1 Size: A-536
 - 3.3.2 Shape: A-536, A-545
 - 3.3.4 Stress Concentrations: A-71, A-141, A-226, A-382, A-383, A-546, C-110, C-140, C-141
 - 3.4 Surface Factors:
 - 3.4.2 Polishing Techniques: B-273
 - 3.4.3 Surface Finish: A-141
 - 3.4.7 Residual Stresses: A-383, A-546
 - 3.4.9 Other Surface Factors: A-147
 - 3.5 Other Influencing Variables: A-85, A-102
 - 3.5.1 Speed: A-376, A-409, A-410, A-536, B-459, C-140
 - 3.5.2 Mean Stress, Alternating Stress: A-71, A-136, A-141, A-382, B-266, C-140
 - 3.5.3 Combined Stress: A-454, E-54
 - 3.6 Environmental Factors:
 - 3.6.1 Temperature: A-82, A-241, A-327, A-328, A-392, C-20
 - 3.6.1.1 High: A-16, A-50, A-72, A-129, A-136, A-141, A-147, A-334, A-343, A-347, A-381, A-382, A-383, A-392, A-409, A-410, A-416, A-454, A-536, A-546, A-549, B-39, B-329, B-459,

- C-110, C-137, C-138, C-140, C-141, C-175, C-223, C-264, D-25, D-154, E-54
 - 3.6.1.2 Low: A-129
 - 3.6.2 Corrosion and Chemical Attack: C-141
 - 3.6.5 Thermal Cycling, Strain Cycling, Low Cycle Fatigue: A-152, A-206, A-220, A-222, A-329, A-376, A-392, A-416, A-536, A-537, B-461, D-154
 - 3.7 Fatigue Damage and Measurement: B-310
 - 3.7.1 Detection of Damage: A-226, B-465, D-161
 - 3.7.3.1 Prior Stress or Strain History: A-381, A-383, A-546
 - 3.7.3.5 Step, Sequential, Spectrum Tests: A-206, A-383
 - 3.8 Test Methods and Machines:
 - 3.8.1 Fatigue Machines: A-454, B-465
 - 3.8.2 Control Apparatus: B-465
 - 3.8.3 Statistical Approaches: B-310, C-98
 - 3.8.4 Programming of Tests: A-152
 - 3.9 Engineering Problems and Design: A-17
 - 3.9.1 Service Failures: A-267, B-310
 - 3.9.2 Empirical Reduction of Fatigue Information to Formulas: A-537
 - 3.9.3 Application of Fatigue Data in Design: A-129, B-183
 - 3.9.4 Stress-Range Diagrams: A-382, A-454
 - 3.10 Fatigue Properties of Structures and Machines:
 - 3.10.1 Joints and Joining Methods: A-307
 - 3.10.1.3 Spot Welds and Other Fusion Welded Joints: A-35
 - 3.10.2 Other Components of Machines and Structures: A-244, B-421
 - 3.10.2.1 Gears: A-347
 - 3.10.2.2 Bearings: A-549
 - 3.10.3 Large Scale Structural and Machine Members: A-222
 - 3.11 Fatigue Properties of Materials (data-generating studies): A-293, B-52, B-266, B-329, C-137
 - 3.12.2 Historical Summaries: A-477, A-514, C-264
- #### 4. ALUMINUM ALLOYS
- 4.1 Basic Research, Nature of Fatigue: A-119, B-79, D-24
 - 4.1.1 Experimental Materials: A-113, B-111, B-475
 - 4.1.2 Single and Large Crystals: B-82, B-268, B-365, C-42, C-135, C-181
 - 4.1.3 Correlations, Physical Properties: A-444, A-539, A-542
 - 4.1.4 Correlations, Mechanical Properties: A-269, A-285, A-403, A-487, B-420, C-31
 - 4.1.4.2 Damping: A-131, A-192, A-226, A-487, B-152, B-373
 - 4.1.4.3 Tensile and Impact: A-160, A-486, B-269, B-467
 - 4.1.4.4 Creep: A-383, A-546
 - 4.1.5 Deformation and Fracture Mechanisms: A-189, A-383, A-403, A-537, A-539, A-546, B-37, B-111, B-135, B-213, B-217, B-268, B-269, B-275, B-282, B-283, B-284, B-335, B-351, B-409, B-410, B-418, B-437, B-462, B-467, B-474, B-475, C-42, C-77, C-104, E-18, E-52
 - 4.2 Composition and Processing Variables: B-434
 - 4.2.1 Composition: D-160
 - 4.2.1.1 Alloying Elements: A-531, A-537, B-409, B-463, C-31, C-36
 - 4.2.2 Microstructure: A-40, B-36, B-79, C-72, C-104, C-131
 - 4.2.2.1 Grain Size or Particle Size: A-375, A-380, B-111
 - 4.2.2.2 Grain Orientation: B-285
 - 4.2.2.3 Anisotropy: A-26, A-40, A-111, A-250, A-473, B-452, C-16, C-129
 - 4.2.3 Melting, Molding, and Casting Techniques: E-44
 - 4.2.4 Primary and Secondary Fabrication: A-43, A-375, A-385, A-537, B-34, B-379
 - 4.2.4.1 Forging: A-531
 - 4.2.4.3 Forming: A-292
 - 4.2.5 Defects: A-385, B-34, B-131, C-72
 - 4.2.5.2 Porosity: B-456
 - 4.2.6 Heat Treatment (excluding surface hardening): A-375, B-79, B-217, B-285, B-307, B-410, C-31, C-101, C-177, C-193, C-244
 - 4.2.7 Other Factors: A-319, C-178
 - 4.3 Geometric Factors:
 - 4.3.1 Size: A-139, A-151, A-380, B-70, B-229, B-385, B-399, C-15, C-47, C-71, C-121
 - 4.3.2 Shape: A-311, B-131, B-456, C-15, C-55, C-102, C-103
 - 4.3.3 Stress Gradient: A-380
 - 4.3.4 Stress Concentrations: A-59, A-60, A-139, A-142, A-151, A-168, A-171, A-226, A-249, A-250, A-269, A-380, A-383, A-425, A-449, A-452, A-486, A-498, A-506, A-528, A-546, B-42, B-43, B-131, B-140, B-189, B-229, B-379, B-381, B-400, B-404, B-415, B-452, B-456, C-18, C-22, C-26, C-27, C-31, C-47, C-55, C-61, C-121, C-134, E-15, E-24
 - 4.4 Surface Factors: B-285, C-15, C-94, C-244, E-15
 - 4.4.2 Polishing Techniques: A-391, E-43
 - 4.4.5 Surface Hardening, Cold Work: A-5, A-83, A-375, A-550, B-441, E-43
 - 4.4.7 Residual Stresses: A-383, A-546, C-26, C-27
 - 4.4.8 Surface Coatings: C-26, C-27, D-53
 - 4.4.8.1 Electroplated: B-257
 - 4.4.8.2 Other Coatings: A-151, A-350, A-391, B-256, B-257, B-436, C-40, D-80
 - 4.4.9 Other Surface Factors: B-74, D-53
 - 4.5 Other Influencing Variables: B-239
 - 4.5.1 Speed: A-228, A-245, B-444, C-107, D-49
 - 4.5.2 Mean Stress, Alternating Stress: A-111, A-142, A-151, A-425, A-451, A-461, A-484, B-209, B-244, B-306, B-326, B-381, B-404, B-409, C-26, C-27, C-55
 - 4.5.3 Combined Stress: A-111, A-170
 - 4.5.4 Type of Loading: A-26, A-196, A-451, A-531, B-195, B-232, B-400, B-444, E-36
 - 4.6 Environmental Factors: A-344, B-470, E-43
 - 4.6.1 Temperature: A-192, C-55
 - 4.6.1.1 High: A-106, A-131, A-228, A-367, A-383, A-546, B-445
 - 4.6.1.2 Low: B-111, B-209, B-316, B-326
 - 4.6.2 Corrosion and Chemical Attack: A-350, B-20, B-217, B-228, B-285, B-410, B-413, B-444, C-106
 - 4.6.3 Fretting: A-550, C-97, C-172, E-18
 - 4.6.5 Thermal Cycling, Strain Cycling, Low Cycle Fatigue: A-155, A-473, A-537, B-70, B-434, C-32, C-189, D-49
 - 4.6.7 Acoustic: A-455
 - 4.7 Fatigue Damage and Measurement: A-113, A-542, A-559, B-437, B-474, C-26, C-27, C-115
 - 4.7.1 Detection of Damage: A-21, A-131, A-226, A-296, B-140, B-152, B-283, B-284, B-404, B-470

- 4.7.1.1 Prior to Cracking: A-189, A-473, B-135, B-213
 - 4.7.1.2 After Cracking: A-111, A-160, A-473, B-135, B-213
 - 4.7.2 Crack Propagation: A-21, A-119, A-132, A-138, A-139, A-148, A-171, A-242, A-249, A-339, A-341, A-358, A-403, A-461, A-473, A-484, A-485, A-559, B-43, B-70, B-71, B-194, B-290, B-291, B-293, B-381, B-404, B-415, C-2, C-60, C-67, C-78, C-89
 - 4.7.3 Cumulative Damage: A-61, A-117, A-148, A-296, A-337, A-370, A-504, B-64, B-73, B-102, B-444, C-2, C-17, C-61, C-256, E-15
 - 4.7.3.1 Prior Stress or Strain History: A-338, A-383, B-54, B-209, B-272, B-306, B-326, C-41
 - 4.7.3.3 Understressing, Overstressing: B-326, C-48
 - 4.7.3.5 Step, Sequential, Spectrum Tests: A-88, A-115, A-383, A-433, A-436, A-451, A-452, A-498, B-48, B-102, B-136, B-206, B-209, B-452, C-34, C-68, C-234, C-250, C-256
 - 4.8 Test Methods and Machines: A-84
 - 4.8.1 Fatigue Machines: B-94, B-444, C-231
 - 4.8.2 Control Apparatus: B-94, B-444, C-231
 - 4.8.3 Statistical Approaches: C-22, C-98
 - 4.8.3.1 Design of Experiments: C-250
 - 4.8.3.2 Analysis: A-115, A-504, B-378, B-381, B-404, B-444, C-32, C-37, C-80, C-105, C-230
 - 4.9 Engineering Problems and Design: B-131, B-228, D-160
 - 4.9.1 Service Failures: A-419, B-32, B-95, B-166, B-212, B-232
 - 4.9.2 Empirical Reduction of Fatigue Information to Formulas: A-380, A-461, A-486, A-498, A-504, A-506, A-537
 - 4.9.3 Application of Fatigue Data in Design: A-84, A-254, A-270, A-419, A-504, A-528, A-559, B-25, B-346, B-381, B-404, C-220, C-230, C-234, C-250
 - 4.9.4 Stress-Range Diagrams: B-404
 - 4.10 Fatigue Properties of Structures and Machines: B-92
 - 4.10.1 Joints and Joining Methods: A-81, A-196, A-487, A-550, B-53, B-159, B-399
 - 4.10.1.1 Rivets and Riveted Joints: A-181, A-281, A-370, A-526, B-172, B-444, C-40, C-45, C-61, C-68, C-71, C-108, C-136, C-180, C-256
 - 4.10.1.2 Bolts and Bolted Joints: A-11, B-297
 - 4.10.1.3 Spot Welds and Other Fusion Welded Joints: A-35, A-137, A-176, A-462, B-456, D-160
 - 4.10.1.4 Adhesives and Adhesive Joints: B-172, B-386, C-108, C-136, C-180, D-105
 - 4.10.2 Other Components of Machines and Structures: A-455, A-504, B-166, C-246
 - 4.10.3 Large Scale Structural and Machine Members: A-9, A-51, A-81, A-84, A-132, A-148, A-167, A-169, A-170, A-245, A-254, A-296, A-341, A-345, A-419, A-559, B-15, B-21, B-54, B-58, B-87, B-95, B-131, B-206, B-209, B-228, B-232, B-306, B-381, B-388, B-404, B-416, C-2, C-230, C-234, C-239, C-250
 - 4.11 Fatigue Properties of Materials (data-generating studies): A-175, A-210, A-281, A-365, A-385, B-64, B-285, B-316, B-444, C-14, C-31, C-79, C-122, C-192, C-249, D-126, E-8
 - 4.12 Theoretical Discussions, General Reviews: A-67, A-156, A-365, A-433, B-49, B-70, B-76, B-285
 - 4.12.1 Theoretical Treatments, Fatigue and Related Effects: A-330, A-484, B-155, B-454, C-67, C-77, C-115
 - 4.12.2 Historical Summaries: A-484
 - 4.12.3 Bibliographies: B-98
- ## 5. COPPER ALLOYS
- 5.1 Basic Research, Nature of Fatigue: B-193
 - 5.1.2 Single and Large Crystals: A-427, B-222, B-223, B-268, B-365, B-426
 - 5.1.3 Correlations, Physical Properties: A-15, A-444, A-539
 - 5.1.3.1 Resistivity: A-73
 - 5.1.4 Correlations, Mechanical Properties: B-279, B-395, B-420
 - 5.1.4.4 Creep: A-520
 - 5.1.5 Deformation and Fracture Mechanisms: A-109, A-189, A-200, A-213, A-388, A-427, A-520, A-537, A-539, B-123, B-170, B-173, B-222, B-223, B-268, B-274, B-300, B-301, B-302, B-303, B-335, B-343, B-351, B-426, C-183, E-22
 - 5.2 Composition and Processing Variables: B-279, B-434
 - 5.2.1 Composition: D-23
 - 5.2.2 Microstructure: B-91, B-337, B-343, C-118
 - 5.2.2.1 Grain Size or Particle Size: A-86, A-363
 - 5.2.2.3 Anisotropy: A-109
 - 5.2.4 Primary and Secondary Fabrication: A-537
 - 5.2.5 Defects: A-109, E-22
 - 5.2.6 Heat Treatment (excluding surface hardening): B-302, B-395
 - 5.3 Geometric Factors:
 - 5.3.1 Size: C-185
 - 5.3.4 Stress Concentrations: B-435
 - 5.4 Surface Factors:
 - 5.4.2 Polishing Techniques: E-43
 - 5.4.5 Surface Hardening, Cold Work: B-193, E-43
 - 5.4.7 Residual Stresses: B-418
 - 5.4.8 Surface Coatings:
 - 5.4.8.1 Electroplated: A-363, B-339
 - 5.4.9 Other Surface Factors: B-191, C-56
 - 5.5 Other Influencing Variables:
 - 5.5.1 Speed: B-173, D-49
 - 5.5.2 Mean Stress, Alternating Stress: B-435
 - 5.5.4 Type of Loading: B-195
 - 5.6 Environmental Factors: B-470, E-43
 - 5.6.1 Temperature: D-23
 - 5.6.1.1 High: A-86, A-213, B-91
 - 5.6.1.2 Low: B-97, B-316, B-392, B-393, B-426, B-450
 - 5.6.2 Corrosion and Chemical Attack: B-65, B-66, B-91, B-191, B-413, C-56
 - 5.6.5 Thermal Cycling, Strain Cycling, Low Cycle Fatigue: A-537, B-434, D-49
 - 5.7 Fatigue Damage and Measurement:
 - 5.7.1 Detection of Damage: A-21, B-223, B-470
 - 5.7.1.1 Prior to Cracking: A-189, B-123
 - 5.7.2 Crack Propagation: A-21, A-109, A-339, B-300, B-435, C-60
 - 5.8 Test Methods and Machines: A-1
 - 5.8.1 Fatigue Machines: B-97
 - 5.9 Engineering Problems and Design:
 - 5.9.2 Empirical Reduction of Fatigue Information to Formulas: A-537

- 5.11 Fatigue Properties of Materials (data-generating studies):
A-1, A-293, B-196, B-316, C-79, E-49
- 5.12 Theoretical Discussions, General Reviews:
 - 5.12.1 Theoretical Treatments, Fatigue and Related Effects:
A-388, B-155
- 6. MAGNESIUM ALLOYS
- 6.1 Basic Research, Nature of Fatigue:
 - 6.1.4 Correlations, Mechanical Properties:
 - 6.1.4.2 Damping: A-226
- 6.2 Composition and Processing Variables:
 - 6.2.2 Composition:
 - 6.2.2.2 Grain Orientation: A-558
 - 6.2.3 Melting, Molding, and Casting Techniques: A-558
 - 6.2.5 Defects: A-558
- 6.3 Geometric Factors:
 - 6.3.4 Stress Concentrations: A-226, B-435
- 6.4 Surface Factors:
 - 6.4.8 Surface Coatings:
 - 6.4.8.2 Other Coatings: A-8
- 6.5 Other Influencing Variables:
 - 6.5.2 Mean Stress, Alternating Stress: B-435
 - 6.5.4 Type of Loading: A-140
- 6.6 Environmental Factors:
 - 6.6.1 Temperature:
 - 6.6.1.2 Low: B-316
- 6.7 Fatigue Damage and Measurement:
 - 6.7.1 Detection of Damage: A-21, A-226
 - 6.7.2 Crack Propagation: A-21, B-435
- 6.9 Engineering Problems and Design: A-140
- 6.10 Fatigue Properties of Structures and Machines:
 - 6.10.1 Joints and Joining Methods:
 - 6.10.1.3 Spot Welds and Other Fusion Welded Joints:
A-317
- 6.11 Fatigue Properties of Materials (data-generating studies):
A-140, B-316
- 6.12 Theoretical Discussions, General Reviews:
 - 6.12.3 Bibliographies: B-98
- 7. TITANIUM ALLOYS
- 7.1 Basic Research, Nature of Fatigue:
 - 7.1.4 Correlations, Mechanical Properties: A-165
 - 7.1.4.2 Damping: A-101
 - 7.1.5 Deformation and Fracture Mechanisms: A-478, A-515,
B-329
- 7.2 Composition and Processing Variables:
 - 7.2.1 Composition:
 - 7.2.1.1 Alloying Elements: A-165
 - 7.2.1.2 Interstitials: A-227
 - 7.2.2 Microstructure: C-214
 - 7.2.2.1 Grain Size or Particle Size: A-165
 - 7.2.4 Primary and Secondary Fabrication: A-91, A-284,
C-214
 - 7.2.4.3 Forming: A-292
 - 7.2.6 Heat Treatment (excluding surface hardening): A-91,
A-185
 - 7.2.7 Other Factors: A-33, A-312
- 7.3 Geometric Factors:
 - 7.3.4 Stress Concentrations: A-104
- 7.4 Surface Factors: A-23, C-94, C-168
 - 7.4.1 Machining Techniques: A-510
 - 7.4.3 Surface Finish: A-280
 - 7.4.5 Surface Hardening, Cold Work: A-510
 - 7.4.7 Residual Stresses: A-284, A-510, B-327
- 7.5 Other Influencing Variables:
 - 7.5.1 Speed: A-515
 - 7.5.2 Mean Stress, Alternating Stress: A-515, E-27, E-41
 - 7.5.4 Type of Loading: B-195
- 7.6 Environmental Factors:
 - 7.6.1 Temperature:
 - 7.6.1.1 High: A-42, A-173, A-478, B-329, B-445, C-76
 - 7.6.3 Fretting: A-262, A-284
 - 7.6.5 Thermal Cycling, Strain Cycling, Low Cycle Fatigue:
A-478
- 7.7 Fatigue Damage and Measurement:
 - 7.7.1 Detection of Damage: A-101
- 7.8 Test Methods and Machines:
 - 7.8.2 Control Apparatus: A-478
- 7.10 Fatigue Properties of Structures and Machines:
 - 7.10.1 Joints and Joining Methods:
 - 7.10.1.2 Bolts and Bolted Joints: A-6, A-70
 - 7.10.1.3 Spot Welds and Other Fusion Welded Joints:
A-35, B-5
- 7.11 Fatigue Properties of Materials (data-generating studies):
A-23, A-104, A-273, B-260, B-327, B-329,
C-214, D-64
- 8. OTHER METALLIC MATERIALS
- 8.1 Basic Research, Nature of Fatigue:
 - 8.1.2 Single and Large Crystals: A-384, B-376
 - 8.1.4 Correlations, Mechanical Properties: A-130, B-176,
B-427
 - 8.1.4.2 Damping: C-225
 - 8.1.4.3 Tensile and Impact: D-113
 - 8.1.4.4 Creep: B-175, B-448
 - 8.1.5 Deformation and Fracture Mechanisms: A-478, A-537,
B-222, B-351, B-407
- 8.2 Composition and Processing Variables:
 - 8.2.1 Composition:
 - 8.2.1.1 Alloying Elements: A-124, D-113
 - 8.2.2 Microstructure: A-372, B-337, B-376
 - 8.2.2.1 Grain Size or Particle Size: A-376
 - 8.2.4 Primary and Secondary Fabrication: A-124
- 8.3 Geometric Factors:
 - 8.3.4 Stress Concentrations: C-141
- 8.5 Other Influencing Variables:
 - 8.5.1 Speed: A-376
 - 8.5.3 Combined Stress: A-259
 - 8.5.4 Type of Loading: B-195
- 8.6 Environmental Factors: B-470
 - 8.6.1 Temperature: B-427
 - 8.6.1.1 High: A-211, A-478, A-536, C-141, C-202
 - 8.6.1.2 Low: A-122, B-316, B-376, B-450
 - 8.6.2 Corrosion and Chemical Attack: B-413, C-141

- 8.6.5 Thermal Cycling, Strain Cycling, Low Cycle Fatigue: A-211, A-376, A-478, A-536, A-537, B-427, B-448
- 8.7 Fatigue Damage and Measurement:
 - 8.7.1 Detection of Damage: B-304, B-470
 - 8.7.2 Crack Propagation: A-373
- 8.8 Test Methods and Machines:
 - 8.8.2 Control Apparatus: A-478
- 8.9 Engineering Problems and Design:
 - 8.9.2 Empirical Reduction of Fatigue Information to Formulas: A-537
- 8.10 Fatigue Properties of Structures and Machines:
 - 8.10.1 Joints and Joining Methods: A-130
 - 8.10.2 Other Components of Machines and Structures:
 - 8.10.2.2 Bearings: C-109, D-2
- 8.11 Fatigue Properties of Materials (data-generating studies): A-12, A-14, A-193, A-211, B-196, B-316, C-109
- 8.12 Theoretical Discussions, General Reviews:
 - 8.12.1 Theoretical Treatments, Fatigue and Related Effects: A-355, B-448

9. WOOD AND PLASTICS

- 9.1 Basic Research, Nature of Fatigue:
 - 9.1.4 Correlations, Mechanical Properties: A-472
 - 9.1.4.4 Creep: B-391
- 9.2 Composition and Processing Variables:
 - 9.2.1 Composition:
 - 9.2.1.3 Reinforcing, Laminating or Filler Materials: A-89, A-534, B-231, B-391
 - 9.2.2.3 Anisotropy: A-534
 - 9.2.3 Melting, Molding, and Casting Techniques: A-247
 - 9.2.7 Other Factors: A-89
- 9.3 Geometric Factors:
 - 9.3.4 Stress Concentrations: A-89, A-212, A-534
- 9.4 Surface Factors: A-247
- 9.5 Other Influencing Variables:
 - 9.5.2 Mean Stress, Alternating Stress: A-89, A-212
- 9.6 Environmental Factors:
 - 9.6.1 Temperature:
 - 9.6.1.1 High: A-89, A-212
 - 9.6.6 Humidity: A-89, A-212, A-534
- 9.7 Fatigue Damage and Measurement:
 - 9.7.3 Cumulative Damage:
 - 9.7.3.5 Step, Sequential, Spectrum Tests: A-258, B-354
- 9.8 Test Methods and Machines: B-391
- 9.9 Engineering Problems and Design: B-391
- 9.10 Fatigue Properties of Structures and Machines: B-231
 - 9.10.3 Large Scale Structural and Machine Members: A-37
- 9.11 Fatigue Properties of Materials (data-generating studies): A-13, A-204, A-212, B-271

10. CERAMIC MATERIALS

- 10.2 Other Components of Machines and Structures:
 - 10.2.2 Microstructure: A-309

- 10.6 Environmental Factors:
 - 10.6.5 Thermal Cycling, Strain, Cycling, Low Cycle Fatigue: B-383

11. CEMENT, MORTAR, CONCRETE

- 11.1 Basic Research, Nature of Fatigue:
 - 11.1.4 Correlations, Mechanical Properties: D-107
- 11.2 Composition and Processing Variables:
 - 11.2.1 Composition:
 - 11.2.1.3 Reinforcing, Laminating or Filler Materials: A-411, A-532, A-540, D-107
 - 11.2.1.4 Prestressing Members or Materials: A-499
 - 11.2.7 Other Factors: A-397
- 11.3 Geometric Factors:
 - 11.3.1 Size: A-93
 - 11.3.2 Shape: A-540
- 11.5 Other Influencing Variables:
 - 11.5.2 Mean Stress, Alternating Stress: A-497
 - 11.5.4 Type of Loading: A-499
- 11.7 Fatigue Damage and Measurement: A-411
 - 11.7.2 Crack Propagation: D-107
- 11.8 Test Methods and Machines:
 - 11.8.3 Statistical Approaches:
 - 11.8.3.2 Analysis: A-93, A-480
- 11.9 Engineering Problems and Design:
 - 11.9.2 Empirical Reduction of Fatigue Information to Formulas: A-93
 - 11.9.4 Stress-Range Diagrams: A-497
- 11.10 Fatigue Properties of Structures and Machines:
 - 11.10.2 Other Components of Machines and Structures: A-540
 - 11.10.3 Large Scale Structural and Machine Members: A-39, A-232, A-326
- 11.11 Fatigue Properties of Materials (data-generating studies): A-362, B-328
- 11.12 Theoretical Discussions, General Reviews:
 - 11.12.1 Theoretical Treatments, Fatigue and Related Effects: A-305
 - 11.12.2 Historical Summaries: A-234, A-361, A-499

12. JOINTS AND JOINING METHODS

- 12.1 Basic Research, Nature of Fatigue:
 - 12.1.4 Correlations, Mechanical Properties: A-487
 - 12.1.4.2 Damping: A-487, A-489
- 12.2 Composition and Processing Variables:
 - 12.2.5 Defects: B-455, D-50
 - 12.2.5.1 Inclusions: B-455
 - 12.2.5.2 Porosity: B-455, B-456
 - 12.2.6 Heat Treatment (excluding surface hardening): B-457
- 12.3 Geometric Factors:
 - 12.3.2 Shape: B-457
 - 12.3.4 Stress Concentrations: B-456, B-457, C-61
- 12.4 Surface Factors: B-457
 - 12.4.5 Surface Hardening, Cold Work: A-550
- 12.6 Environmental Factors:
 - 12.6.3 Fretting: A-550
 - 12.6.7 Acoustic: A-489

- 12.7 Fatigue Damage and Measurement:
 - 12.7.3 Cumulative Damage: C-61, C-256
 - 12.7.3.5 Step, Sequential, Spectrum Tests: C-68, C-256
 - 12.8 Test Methods and Machines: C-274
 - 12.8.1 Fatigue Machines: B-458
 - 12.9 Engineering Problems and Design:
 - 12.9.1 Service Failures: A-294
 - 12.9.3 Application of Fatigue Data in Design: C-128
 - 12.10 Fatigue Properties of Structures and Machines: A-127
 - 12.10.1 Joints and Joining Methods: A-487, A-550, B-399, D-117
 - 12.10.1.1 Rivets and Riveted Joints: A-181, A-182, A-281, A-282, A-284, A-526, B-172, B-306, B-334, C-45, C-61, C-68, C-71, C-124, C-136, C-256
 - 12.10.1.2 Bolts and Bolted Joints: B-297, C-124
 - 12.10.1.3 Spot Welds and Other Fusion Welded Joints: A-114, A-130, A-164, A-195, A-253, A-268, A-294, A-553, B-199, B-210, B-225, B-237, B-278, B-309, B-349, B-456, B-457, B-458, C-53, C-87, C-93, C-127, C-128, C-133, C-215, D-38, D-45, D-50, D-51, D-62, D-65, D-138, D-146, D-156
 - 12.10.1.4 Adhesives and Adhesive Joints: A-471, A-489, B-172, C-39, C-120, C-136, C-274
 - 12.10.2 Other Components of Machines and Structures: A-256, A-290, B-246, B-336, B-458, C-139
 - 12.10.3 Large Scale Structural and Machine Members: A-253, A-268, A-294, C-127, C-133
 - 12.11 Fatigue Properties of Materials (data-generating studies): A-281, A-282, B-349
 - 12.12 Theoretical Discussions, General Reviews:
 - 12.2.2 Historical Summaries: B-455
- 13. OTHER NONMETALLIC MATERIALS**
- 13.1 Basic Research, Nature of Fatigue:
 - 13.1.1 Experimental Materials: B-430
 - 13.1.2 Single and Large Crystals: A-348
 - 13.1.5 Deformation and Fracture Mechanisms: B-430
 - 13.2 Composition and Processing Variables:
 - 13.2.1.1 Alloying Elements: A-336
 - 13.2.1.2 Interstitials: A-336
 - 13.2.1.3 Reinforcing, Laminating or Filler Materials: A-197
 - 13.2.2.3 Anisotropy: A-197
 - 13.3 Geometric Factors:
 - 13.3.4 Stress Concentrations: A-197
 - 13.5 Other Influencing Variables:
 - 13.5.4 Type of Loading: A-197
 - 13.6 Environmental Factors:
 - 13.6.1 Temperature: A-315
 - 13.8 Test Methods and Machines:
 - 13.8.2 Control Apparatus: A-315
 - 13.9 Engineering Problems and Design: A-79
 - 13.12 Theoretical Discussions, General Reviews: A-351