

SUBJECT INDEX TO 1964 REFERENCES

1. GENERAL (NO SPECIFIC MATERIAL)

- 1.1 Basic research, nature of fatigue: A-123, A-172, B-81, C-8
 - 1.1.4 Correlations, mechanical properties: D-6
 - 1.1.4.1 Anelasticity: E-91
 - 1.1.4.3 Tensile and impact: A-99, A-119
 - 1.1.5 Deformation and fracture mechanisms: A-59, A-137, D-23, E-91
- 1.2 Composition and processing variables: A-2
 - 1.2.1 Composition:
 - 1.2.1.4 Prestressing members or materials: D-20, D-38
 - 1.2.2 Microstructure:
 - 1.2.2.1 Grain size or particle size: A-148
 - 1.2.5 Defects: A-96, E-7, E-21
- 1.3 Geometric factors: E-57
 - 1.3.1 Size: A-111, E-21
 - 1.3.3 Stress gradient: A-99, A-116
 - 1.3.4 Stress concentrations: A-36, A-68, A-116, A-121, A-136, A-137, A-160, A-183, E-21, E-93
- 1.4 Surface factors:
 - 1.4.1 Machining techniques: E-7
 - 1.4.2 Polishing techniques: E-7
 - 1.4.3 Surface finish: E-7, E-121
 - 1.4.4 Scratch direction: E-7
 - 1.4.5 Surface hardening, cold work: A-152, E-7
 - 1.4.6 Surface hardening, heat treatment: A-152, E-7
 - 1.4.6.1 Carburizing: E-7
 - 1.4.6.2 Nitriding: E-7
 - 1.4.7 Residual stresses: A-119, A-156
 - 1.4.8 Surface coatings:
 - 1.4.8.1 Electroplated: E-7, E-8
 - 1.4.8.2 Other coatings: E-7
 - 1.4.9 Other surface factors: E-7
- 1.5 Other influencing variables: B-88
 - 1.5.1 Speed: A-160
 - 1.5.2 Mean stress, alternating stress: A-116
 - 1.5.3 Combined stress: A-36
 - 1.5.4 Type of loading: A-121, A-146, B-9, C-18, D-1, E-49, E-57, E-91, E-98
- 1.6 Environmental factors:
 - 1.6.1 Temperature: A-151
 - 1.6.1.1 High: A-17, A-48, A-116, A-120, A-149, A-177, B-12, E-49
 - 1.6.1.2 Low: A-116, B-85
 - 1.6.2 Corrosion and chemical attack: A-2, B-72, D-25, E-9
 - 1.6.3 Fretting: B-55
 - 1.6.5 Thermal cycling, strain cycling, low cycle fatigue: A-17, A-49, A-65, A-75, A-114, A-121, A-155, D-3, D-21, D-32, E-24, E-49, E-123
 - 1.6.7 Acoustic: A-146
- 1.7 Fatigue damage and measurement: A-121, D-9
 - 1.7.1 Detection of damage: B-62, C-19
 - 1.7.1.1 Prior to cracking: A-96, A-116, E-80
 - 1.7.1.2 After cracking: A-116, A-165
 - 1.7.2 Crack propagation: A-111, A-116, A-123, A-165, A-177, D-9, D-36
 - 1.7.3 Cumulative damage: A-47, A-72, A-78, A-98, A-109, A-115, A-116, A-118, E-110
 - 1.7.3.1 Prior stress or strain history: A-116
 - 1.7.3.3 Understressing, overstressing: A-119
 - 1.7.3.5 Step, sequential, spectrum tests: A-20, A-78, A-92, E-93, E-94
- 1.8 Test methods and machines: A-38, A-54, A-66, A-75, A-89, A-90, A-122, A-129, A-146, A-176, B-9, B-54, D-2, D-11, D-12, D-17, D-24, D-26, D-27, D-31, D-33, D-36, D-41
 - 1.8.1 Fatigue machines: A-30, A-45, A-120, A-159, A-191, B-9, B-69, B-74, B-80, B-85, D-29, E-24, E-48, E-52, E-54, E-57, E-87, E-88, E-98, E-111, E-113, E-128
 - 1.8.2 Control apparatus: B-67, B-74, B-82, D-7, E-57, E-88
 - 1.8.3 Statistical approaches: A-166, B-45, B-53, C-2, C-18, D-39
 - 1.8.3.1 Design of experiments: A-13
 - 1.8.3.2 Analysis: A-68, A-83, A-106, A-166, B-32
 - 1.8.4 Programming of tests: A-107, E-54, E-94, E-110, E-128
- 1.9 Engineering problems and design: A-2, A-47, A-90, A-99, A-102, A-130, E-38
 - 1.9.1 Service failures: A-153, B-61, B-72, E-123, E-128
 - 1.9.2 Empirical reduction of fatigue information to formulas: D-13, D-21, E-74, E-82, E-83, E-84
 - 1.9.3 Application of fatigue data in design: A-17, A-49, A-58, A-101, A-107, A-136, A-159, B-29, B-45, B-61, E-70, E-74, E-110
- 1.10 Fatigue properties of structures and machines: A-47, A-60, A-61, A-66, A-89, A-90, A-106, A-107, A-151, B-9, B-54, B-61, E-74
 - 1.10.1 Joints and joining methods:
 - 1.10.1.1 Rivets and riveted joints: D-5
 - 1.10.1.2 Bolts and bolted joints: B-61, D-5
 - 1.10.1.3 Spot welds and other fusion welded joints: A-47, B-43
 - 1.10.2 Other components of machines and structures: A-101, A-102, A-129, A-130, A-176, B-9, E-80, E-98, E-128
 - 1.10.2.1 Gears: A-159, B-29
 - 1.10.2.2 Bearings: A-2, A-96, B-38
 - 1.10.3 Large scale structural and machine members: A-14, A-28, A-38, A-48, A-92, B-9, B-12, B-45, B-61, B-88, C-2, C-18, C-23, E-38, E-110, E-123
- 1.11 Fatigue properties of materials (data-generating studies): A-145, E-7, E-8, E-9, E-10
- 1.12 Theoretical discussions, general reviews: A-9, A-13, A-20, A-72, A-116, A-122, A-123, B-5, B-16, B-55, E-32, E-38, E-74, E-80
 - 1.12.1 Theoretical treatments, fatigue and related effects:

- A-64, A-114, A-136, B-48, B-53, E-21, E-65, E-82, E-83, E-84, E-91, E-95, E-122
- 1.12.2 Historical summaries: A-65, B-73, C-10, E-7
- 1.12.3 Bibliographies: A-10, E-7, E-12
- 1.12.4 Books: A-27, A-33, A-117, E-5, E-12
2. IRON AND STEEL
- 2.1 Basic research, nature of fatigue: B-49, C-11, C-20, D-15, D-33, D-40
- 2.1.1 Experimental materials: E-67
- 2.1.3 Correlations, physical properties: B-30, E-67
- 2.1.4 Correlations, mechanical properties: A-85, A-144, B-30, C-17, E-37, E-62, E-64, E-72, E-77, E-96, E-97
- 2.1.4.1 Anelasticity: A-19, A-191
- 2.1.4.2 Damping: A-135, B-21, E-52
- 2.1.4.3 Tensile and impact: A-97, A-135, E-85, E-105, E-124
- 2.1.4.4 Creep: A-43, E-107, E-131
- 2.1.5 Deformation and fracture mechanisms: A-1, A-43, A-79, A-127, A-135, A-190, B-14, B-78, D-40, E-30, E-32, E-42, E-75, E-77, E-97, E-100, E-126, E-130, E-131
- 2.2 Composition and processing variables: A-134, C-1, C-10
- 2.2.1 Composition: A-56, A-144, C-17, E-77, E-130
- 2.2.1.1 Alloying elements: A-85, C-9, C-14, E-18, E-37, E-39, E-60, E-72, E-81, E-105
- 2.2.1.3 Reinforcing, laminating or filler materials: E-69
- 2.2.1.4 Prestressing members or materials: A-55, A-135
- 2.2.2 Microstructure: C-22, E-37, E-81
- 2.2.2.1 Grain size or particle size: A-85, A-135, C-17, C-21, E-77, E-78
- 2.2.2.3 Anisotropy: A-85, E-30, E-33
- 2.2.3 Melting, molding, and casting techniques: A-63, A-154, A-192, B-27, C-26, E-81
- 2.2.4 Primary and secondary fabrication: A-85, A-144
- 2.2.4.1 Forging: A-16, B-4, E-64, E-96
- 2.2.4.2 Rolling: A-16, E-18, E-30, E-81, E-99, E-100
- 2.2.4.3 Forming: E-61, E-116
- 2.2.5 Defects: A-174, A-178
- 2.2.5.1 Inclusions: A-126, A-154, A-178, B-27, B-40, B-60, C-1, E-23, E-61, E-81
- 2.2.5.2 Porosity: A-126, A-154, A-174, A-192, E-6, E-19
- 2.2.6 Heat treatment (excluding surface hardening): A-50, A-74, A-85, A-135, A-144, B-21, B-27, B-50, B-76, C-14, C-21, C-22, D-34, E-18, E-60, E-61, E-62, E-64, E-77, E-96, E-105
- 2.2.7 Other factors: E-69
- 2.3 Geometric factors: A-70, D-34
- 2.3.1 Size: A-70, A-95, A-139, A-144, B-4, C-1, C-22, D-19, E-21, E-63, E-73
- 2.3.2 Shape: A-144, C-26, E-19, E-69, E-73, E-77
- 2.3.3 Stress gradient: A-97
- 2.3.4 Stress concentrations: A-16, A-56, A-82, A-100, A-139, A-170, A-192, B-1, B-13, B-56, C-14, D-3, D-37, E-3, E-6, E-19, E-21, E-22, E-23, E-45, E-48, E-50, E-67, E-69, E-72, E-73, E-85, E-97, E-105, E-124, E-130, E-131
- 2.4 Surface factors: C-1, E-17, E-61
- 2.4.1 Machining techniques: A-3, A-144, B-4
- 2.4.2 Polishing techniques: A-144
- 2.4.3 Surface finish: A-86
- 2.4.5 Surface hardening, cold work: A-4, A-86, A-159, B-13, B-19, E-10, E-16, E-81, E-120
- 2.4.6 Surface hardening, heat treatment: A-74, A-97, B-86, C-24, E-72, E-73, E-86, E-97
- 2.4.6.1 Carburizing: A-159, E-11, E-27, E-106
- 2.4.6.2 Nitriding: A-159, B-24, E-11, E-27, E-106
- 2.4.7 Residual stresses: A-7, A-12, A-56, A-57, A-74, A-178, B-13, E-16, E-23, E-72, E-73, E-86, E-101, E-106
- 2.4.8 Surface coatings: A-105, B-20
- 2.4.9 Other surface factors: B-6, B-76
- 2.5 Other influencing variables:
- 2.5.1 Speed: A-43, A-173, A-191, B-78, E-18, E-35, E-36, E-107, E-111, E-126, E-131
- 2.5.2 Mean stress, alternating stress: A-16, A-55, A-126, A-139, B-78, B-79, E-81, E-121, E-122
- 2.5.3 Combined stress: A-70, B-20
- 2.5.4 Type of loading: C-7, D-3, D-16, D-34, E-13, E-22, E-33, E-37, E-47, E-48, E-54, E-62, E-77, E-107
- 2.6 Environmental factors:
- 2.6.1 Temperature: A-85, C-9, D-8, E-61, E-62
- 2.6.1.1 High: A-43, A-73, A-82, A-191, B-79, E-13, E-21, E-47, E-91, E-127
- 2.6.1.2 Low: A-135, A-157, A-175, E-18, E-21, E-85
- 2.6.2 Corrosion and chemical attack: A-32, A-105, A-173, D-8, D-16, E-17, E-20, E-30, E-35, E-36, E-119
- 2.6.3 Fretting: A-45, D-28, E-17, E-30
- 2.6.4 Radiation: A-73
- 2.6.5 Thermal cycling, strain cycling, low cycle fatigue: A-39, A-43, A-50, A-69, A-95, A-146, A-164, A-170, A-175, D-3, D-33, E-13, E-20, E-22, E-37, E-42, E-43, E-46, E-47, E-48, E-52, E-62, E-75, E-107, E-124, E-127
- 2.7 Fatigue damage and measurement: D-15, E-99
- 2.7.1 Detection of damage: A-178, E-16, E-37, E-77, E-130
- 2.7.1.1 Prior to cracking: C-20, E-91
- 2.7.1.2 After cracking: A-16, B-14, E-23, E-39, E-63, E-97
- 2.7.2 Crack propagation: A-1, A-50, A-76, A-79, A-100, A-103, A-104, A-174, A-175, B-36, B-37, B-76, D-36, E-20, E-24, E-33, E-36, E-37, E-39, E-72, E-75, E-77, E-97, E-100, E-101, E-119, E-130
- 2.7.3 Cumulative damage: A-19, A-150, B-1, C-7, E-35, E-116, E-117, E-122, E-130
- 2.7.3.1 Prior stress or strain history: B-50, D-40, E-130
- 2.7.3.2 Rest periods: B-1, E-36
- 2.7.3.3 Understressing, overstressing: E-52, E-53, E-116, E-117, E-130
- 2.7.3.5 Step, sequential, spectrum tests: A-150, A-191, B-56, E-15, E-45, E-50, E-51, E-97, E-116, E-117, E-118
- 2.8 Test methods and machines: A-73, A-134, D-41
- 2.8.1 Fatigue machines: A-144, B-7, B-8, B-10, D-37, E-15, E-17, E-81, E-99
- 2.8.2 Control apparatus: A-16
- 2.8.3 Statistical approaches: B-22
- 2.8.3.2 Analysis: A-144
- 2.8.4 Programming of tests: B-86, E-99, E-118
- 2.9 Engineering problems and design: A-55, B-15, B-84, E-38
- 2.9.1 Service failures: A-105, B-3, E-24, E-100, E-119
- 2.9.2 Empirical reduction of fatigue information to formulas: A-139, B-36, E-35, E-87, E-117

- 2.9.3 Application of fatigue data in design: A-16, A-70, A-95, A-104, A-139, E-1, E-86
 - 2.9.4 Stress-range diagrams: A-139, A-144, B-86
 - 2.10 Fatigue properties of structures and machines: B-15, E-15, E-38
 - 2.10.1 Joints and joining methods: E-103
 - 2.10.1.1 Rivets and riveted joints: A-97, A-139
 - 2.10.1.2 Bolts and bolted joints: A-105, A-180
 - 2.10.1.3 Spot welds and other fusion welded joints: A-3, A-4, A-26, A-55, A-70, A-126, A-146, B-1, B-3, B-13, B-19, B-40, B-60, B-69, C-7, C-15, C-26, D-14, E-3, E-87, E-88, E-124
 - 2.10.2 Other components of machines and structures: E-30, E-61, E-88, E-99, E-100, E-120
 - 2.10.2.1 Gears: E-1, E-17, E-39, E-111
 - 2.10.2.2 Bearings: A-134, B-7, B-8, B-10, D-22, E-18, E-23, E-78
 - 2.10.3 Large scale structural and machine members: A-5, A-16, A-55, A-70, A-76, A-95, A-150, B-1, B-3, B-4, B-19, E-101, E-119
 - 2.11 Fatigue properties of materials (data-generating studies): A-5, A-26, A-82, A-145, B-20, E-1, E-11, E-27, E-81, E-106
 - 2.12 Theoretical discussion, general reviews: E-1, E-2, E-38, E-44, E-61, E-76, E-103
 - 2.12.1 Theoretical treatments, fatigue and related effects: A-192, E-33, E-42, E-50, E-51, E-97, E-117, E-126, E-127
 - 2.12.2 Historical summaries: A-171
- ### 3. CORROSION AND HEAT-RESISTANT MATERIALS
- 3.1 Basic nature of fatigue:
 - 3.1.3 Correlations, physical properties: B-30
 - 3.1.3.2 Thermal expansion: E-41
 - 3.1.4 Correlations, mechanical properties: A-184, B-30
 - 3.1.4.3 Tensile and impact: E-85
 - 3.1.5 Deformation and fracture mechanisms: A-167, A-184, E-40, E-89
 - 3.2 Composition and processing variables:
 - 3.2.1 Composition: B-33, C-13
 - 3.2.4 Primary and secondary fabrication:
 - 3.2.4.2 Rolling: E-98
 - 3.2.5 Defects:
 - 3.2.5.1 Inclusions: E-40
 - 3.3 Geometric factors:
 - 3.3.1 Size: E-63, E-98
 - 3.3.2 Shape: E-98, E-109
 - 3.3.4 Stress concentrations: A-62, A-100, A-142, E-85, E-89, E-109
 - 3.4 Surface factors:
 - 3.4.1 Machining techniques: E-40
 - 3.4.6 Surface hardening, heat treatment:
 - 3.4.6.2 Nitriding: B-24
 - 3.4.8 Surface coatings: C-5
 - 3.4.9 Other surface factors: A-184
 - 3.5 Other influencing variables:
 - 3.5.4 Type of loading: B-87, E-63
 - 3.6 Environmental factors:
 - 3.6.1 Temperature: A-71, A-167, E-109
 - 3.6.1.1 High: A-81, E-13, E-40, E-41, E-89
 - 3.6.1.2 Low: A-81, A-186, E-85
 - 3.6.2 Corrosion and chemical attack: C-5, E-9, E-40
 - 3.6.5 Thermal cycling, strain cycling, low cycle fatigue: B-33, E-13, E-40, E-41, E-42, E-113
 - 3.6.8 Vacuum: A-167, E-40
 - 3.7 Fatigue damage and measurement:
 - 3.7.1 Detection of damage:
 - 3.7.1.2 After cracking: E-63
 - 3.7.2 Crack propagation: A-62, A-81, A-100, B-36, B-37
 - 3.7.3 Cumulative damage:
 - 3.7.3.3 Understressing, overstressing: E-53
 - 3.7.3.4 Coaxing: E-89
 - 3.8 Test methods and machines:
 - 3.8.3 Statistical approaches:
 - 3.8.3.1 Design of experiments: A-186
 - 3.8.4 Programming of tests: A-186
 - 3.9 Engineering problems and design:
 - 3.9.2 Empirical reduction of fatigue information to formulas: B-33, E-41
 - 3.9.3 Application of fatigue data in design: A-71
 - 3.10 Fatigue properties of structures and machines:
 - 3.10.1 Joints and joining methods:
 - 3.10.1.2 Bolts and bolted joints: C-5
 - 3.10.1.3 Spot welds and other fusion welded joints: A-142
 - 3.11 Fatigue properties of materials (data-generating studies): A-62, A-71, A-81, A-142, E-9
 - 3.12 Theoretical discussions, general reviews: E-44
 - 3.12.1 Theoretical treatments, fatigue and related effects: A-184
- ### 4. ALUMINUM ALLOYS
- 4.1 Basic research, nature of fatigue: C-11
 - 4.1.2 Single and large crystals: B-57
 - 4.1.4 Correlations, mechanical properties: A-37, E-66
 - 4.1.4.2 Damping: E-66
 - 4.1.4.4 Creep: C-12
 - 4.1.5 Deformation and fracture mechanisms: A-1, A-15, A-40, A-44, A-141, B-14, B-31, B-39, B-57, B-77
 - 4.2 Composition and processing variables: A-35, A-88
 - 4.2.1 Composition: A-169, E-66
 - 4.2.1.1 Alloying elements: A-42, A-140, B-59, E-4, E-29
 - 4.2.2 Microstructure: A-42, A-140, A-141
 - 4.2.2.1 Grain size or particle size: A-169
 - 4.2.2.2 Grain orientation: A-113
 - 4.2.3 Melting, molding, and casting techniques: A-138, A-169, E-34
 - 4.2.4 Primary and secondary fabrication: A-93, A-169
 - 4.2.4.1 Forging: B-59, E-34
 - 4.2.5 Defects:
 - 4.2.5.2 Porosity: A-169
 - 4.2.6 Heat treatment (excluding surface hardening): A-88, A-169, B-42, E-29, E-66
 - 4.3 Geometric factors: A-35
 - 4.3.1 Size: B-42
 - 4.3.2 Shape: B-25, B-68
 - 4.3.4 Stress concentrations: A-67, A-68, A-87, A-91, A-100, A-169, B-26, B-31, E-93

- 4.4 Surface factors: A-35
 - 4.4.1 Machining techniques: A-169
 - 4.4.5 Surface hardening, cold work: E-10
 - 4.4.7 Residual stresses: A-77, A-87
 - 4.4.8 Surface coatings: A-112, B-42, B-68, C-6
 - 4.4.8.2 Other coatings: A-169
 - 4.4.9 Other surface factors: B-26
- 4.5 Other influencing variables: A-35
 - 4.5.1 Speed: A-173, B-31
 - 4.5.2 Mean stress, alternating stress: A-41, A-44, B-34
 - 4.5.4 Type of loading: A-67, A-93, C-12, E-66
- 4.6 Environmental factors: A-35
 - 4.6.1 Temperature:
 - 4.6.1.1 High: A-88, A-169, C-12, E-29, E-34
 - 4.6.1.2 Low: A-37, A-88, A-93, A-157, A-158, A-169, A-186
 - 4.6.2 Corrosion and chemical attack: A-108, A-112, A-173
 - 4.6.3 Fretting: B-18
 - 4.6.4 Radiation: E-56
 - 4.6.5 Thermal cycling, strain cycling, low cycle fatigue:
 - A-44, A-155, E-13, E-46, E-56
 - 4.6.6 Humidity: A-8, A-15, B-28
 - 4.6.7 Acoustic: B-23
 - 4.6.8 Vacuum: A-40, A-41
- 4.7 Fatigue damage and measurement: A-37
 - 4.7.1 Detection of damage:
 - 4.7.1.1 Prior to cracking: A-42, B-39, B-77
 - 4.7.1.2 After cracking: A-15, B-14
 - 4.7.2 Crack propagation: A-1, A-40, A-41, A-67, A-76, A-100, A-140, A-141, B-22, B-34, B-36, B-37, B-40, B-68
 - 4.7.3 Cumulative damage: C-12, E-110
 - 4.7.3.1 Prior stress or strain history: A-44, A-77
 - 4.7.3.5 Step, sequential, spectrum tests: A-77, A-128, E-34, E-93
- 4.8 Test methods and machines: E-58
 - 4.8.1 Fatigue machines: A-93, A-186
 - 4.8.2 Control apparatus: A-93
 - 4.8.3 Statistical approaches:
 - 4.8.3.1 Design of experiments: A-186
 - 4.8.3.2 Analysis: B-46, B-47
 - 4.8.4 Programming of tests: A-128, B-46, B-47, E-110
- 4.9 Engineering problems and design: A-35, A-52
 - 4.9.1 Service failures: B-70, B-71
 - 4.9.2 Empirical reduction of fatigue information to formulas:
 - A-133, B-36
- 4.10 Fatigue properties of structures and machines: A-52
 - 4.10.1 Joints and joining methods: A-87
 - 4.10.1.1 Rivets and riveted joints: A-133, B-42, E-31
 - 4.10.1.2 Bolts and bolted joints: A-133
 - 4.10.1.3 Spot welds and other fusion welded joints: A-37, A-91, A-133, B-25, E-4, E-59, E-112
 - 4.10.1.4 Adhesives and adhesive joints: A-181
 - 4.10.3 Large scale structural and machine members: A-76, B-46, B-47, E-110
- 4.11 Fatigue properties of materials (data-generating studies):
 - A-67, A-91, A-108, A-133, A-138, A-158, D-18, E-34
- 4.12 Theoretical discussions, general review: E-58
 - 4.12.1 Theoretical treatments, fatigue and related effects:
 - A-77
 - 4.12.3 Bibliographies: E-58

5. COPPER ALLOYS

- 5.1 Basic research, nature of fatigue: A-189, B-51, E-129
 - 5.1.2 Single and large crystals: A-131, A-132, B-52, B-83
 - 5.1.4 Correlations, mechanical properties: B-83, E-129
 - 5.1.4.1 Anelasticity: A-19
 - 5.1.4.3 Tensile and impact: E-115
 - 5.1.4.4 Creep: B-65, D-10
 - 5.1.5 Deformation and fracture mechanisms: A-131, A-132, A-188, A-189, B-17, B-58, B-63, B-64, B-66, D-10, D-30, E-28, E-129
- 5.2 Composition and processing variables: C-10
 - 5.2.2 Microstructure: A-188, B-64, E-115
 - 5.2.2.1 Grain size or particle size: E-115
 - 5.2.2.2 Grain orientation: B-66
 - 5.2.4 Primary and secondary fabrication:
 - 5.2.4.2 Rolling: E-98
 - 5.2.5 Defects:
 - 5.2.5.2 Porosity: B-58
 - 5.2.6 Heat treatment (excluding surface hardening): B-58, E-114
- 5.3 Geometric factors:
 - 5.3.1 Size: E-98
 - 5.3.2 Shape: E-98
 - 5.3.4 Stress concentrations: E-22
- 5.4 Surface factors:
 - 5.4.7 Residual stresses: E-28
- 5.5 Other influencing variables:
 - 5.5.2 Mean stress, alternating stress: A-131, A-188
 - 5.5.3 Combined stress: B-65
 - 5.5.4 Type of loading: E-22
- 5.6 Environmental factors:
 - 5.6.1 Temperature:
 - 5.6.1.1 High: B-51
 - 5.6.2 Corrosion and chemical attack: E-114
 - 5.6.5 Thermal cycling, strain cycling, low cycle fatigue:
 - A-131, B-83, E-22
- 5.7 Fatigue damage and measurement: A-188
 - 5.7.1 Detection of damage: E-28
 - 5.7.1.1 Prior to cracking: E-28
 - 5.7.2 Crack propagation: A-132, B-36, B-37, D-30, E-28
 - 5.7.3 Cumulative damage: A-19
- 5.9 Engineering problems and design:
 - 5.9.1 Service failures: E-25
 - 5.9.3 Application of fatigue data in design: A-51
- 5.10 Fatigue properties of structures and machines:
 - 5.10.2 Other components of machines and structures: E-25
- 5.11 Fatigue properties of materials (data-generating studies):
 - A-51, D-18, E-114
- 5.12 Theoretical discussions, general reviews: E-25

6. MAGNESIUM ALLOYS

- 6.2 Composition and processing variables:
 - 6.2.1 Composition:
 - 6.2.1.1 Alloying elements: A-34
 - 6.2.3 Melting, molding, and casting techniques: A-34
 - 6.2.4 Primary and secondary fabrication:
 - 6.2.4.1 Forging: A-34
 - 6.2.6 Heat treatment (excluding surface hardening): A-34

- 6.4 Surface factors:
 - 6.4.7 Residual stresses: A-34
- 6.5 Other influencing variables:
 - 6.5.1 Speed: D-35
- 6.6 Environmental factors:
 - 6.6.1 Temperature: A-34
 - 6.6.4 Radiation: E-56, E-90
 - 6.6.5 Thermal cycling, strain cycling, low cycle fatigue: E-56, E-90

7. TITANIUM ALLOYS

- 7.1 Basic research, nature of fatigue:
 - 7.1.4 Correlations, mechanical properties:
 - 7.1.4.3 Tensile and impact: E-104
- 7.2 Composition and processing variables:
 - 7.2.1 Composition: E-125
 - 7.2.4 Primary and secondary fabrication: A-93
 - 7.2.6 Heat treatment (excluding surface hardening): E-104
- 7.3 Geometric factors:
 - 7.3.1 Size: E-71
 - 7.3.2 Shape: E-109
 - 7.3.4 Stress concentrations: A-62, A-100, A-142, E-104, E-109, E-125
- 7.4 Surface factors:
 - 7.4.5 Surface hardening, cold work: E-125
- 7.5 Other influencing variables:
 - 7.5.2 Mean stress, alternating stress: B-35
 - 7.5.4 Type of loading: A-93
- 7.6 Environmental factors
 - 7.6.1 Temperature: A-71, E-109
 - 7.6.1.1 High: A-81
 - 7.6.1.2 Low: A-81, A-93, A-157, A-158, A-175
 - 7.6.5 Thermal cycling, strain cycling, low cycle fatigue: A-11, A-80, A-164
- 7.7 Fatigue damage and measurement:
 - 7.7.2 Crack propagation: A-62, A-81, A-100, A-175, B-35
- 7.8 Test methods and machines:
 - 7.8.1 Fatigue machines: A-93
 - 7.8.2 Control apparatus: A-93
- 7.9 Engineering problems and design:
 - 7.9.2 Empirical reduction of fatigue information to formulas: B-35
 - 7.9.3 Application of fatigue data in design: A-71
- 7.10 Fatigue properties of structures and machines:
 - 7.10.1 Joints and joining methods:
 - 7.10.1.3 Spot welds and other fusion welded joints: A-142
- 7.11 Fatigue properties of materials (data-generating studies): A-6, A-62, A-71, A-81, A-93, A-142, A-145, A-158, B-2

8. OTHER METALLIC MATERIALS

- 8.1 Basic research, nature of fatigue:
 - 8.1.2 Single and large crystals: A-29
 - 8.1.5 Deformation and fracture mechanisms: A-162, A-179, A-185

- 8.2 Composition and processing variables:
 - 8.2.1 Composition: E-102
 - 8.2.1.1 Alloying elements: C-3
 - 8.2.1.2 Interstitials: A-185
 - 8.2.2 Microstructure:
 - 8.2.2.1 Grain size or particle size: A-182
 - 8.2.5 Defects:
 - 8.2.5.1 Inclusions: A-182
- 8.4 Surface factors:
 - 8.4.3 Surface finish: A-163
 - 8.4.7 Residual stresses: A-163
 - 8.4.8 Surface coatings:
 - 8.4.8.1 Electroplated: A-163
 - 8.4.8.2 Other coatings: A-163, B-11
- 8.5 Other influencing variables:
 - 8.5.1 Speed: B-75
- 8.6 Environmental factors: A-163
 - 8.6.1 Temperature:
 - 8.6.1.1 High: A-30, A-179, A-182
 - 8.6.2 Corrosion and chemical attack: B-75
 - 8.6.3 Fretting: B-11
 - 8.6.5 Thermal cycling, strain cycling, low cycle fatigue: A-179, D-42
 - 8.6.6 Humidity: A-163, B-75
 - 8.6.8 Vacuum: A-163
- 8.7 Fatigue damage and measurement:
 - 8.7.1 Detection of damage:
 - 8.7.1.2 After cracking: E-102
 - 8.7.2 Crack propagation: E-102
- 8.8 Test methods and machines:
 - 8.8.1 Fatigue machines: E-102
- 8.9 Engineering problems and design:
 - 8.9.1 Service failures: B-11
- 8.10 Fatigue properties of structures and machines:
 - 8.10.1 Joints and joining methods:
 - 8.10.1.3 Spot welds and other fusion welded joints: E-14
 - 8.10.2 Other components of machines and structures:
 - 8.10.2.2 Bearings: B-11
- 8.11 Fatigue properties of materials (data-generating studies): A-30, A-145, D-18, E-14

9. WOOD AND PLASTICS

- 9.1 Basic research, nature of fatigue: A-21, A-22, A-23, A-24, A-25, A-31, A-168
 - 9.1.2 Single and large crystals: A-143
 - 9.1.4 Correlations, mechanical properties:
 - 9.1.4.2 Damping: A-53
 - 9.1.4.4 Creep: A-46
 - 9.1.5 Deformation and fracture mechanisms: A-143
- 9.2 Composition and processing variables:
 - 9.2.1 Composition: A-53
 - 9.2.1.3 Reinforcing, laminating or filler materials: A-22, A-23, A-24, A-25, A-31, A-46, A-53, A-168
 - 9.2.1.4 Prestressing members or materials: A-21
 - 9.2.7 Other factors: A-53
- 9.3 Geometric factors:
 - 9.3.4 Stress concentrations: A-53

- 9.4 Surface factors:
 - 9.4.9 Other surface factors: A-53
- 9.5 Other influencing variables: A-143
- 9.6 Environmental factors:
 - 9.6.1 Temperature: A-143
 - 9.6.1.1 High: A-124
 - 9.6.5 Thermal cycling, strain cycling, low cycle fatigue: A-94, A-124
- 9.8 Test methods and machines:
 - 9.8.1 Fatigue machines: C-16
- 9.10 Fatigue properties of structures and machines:
 - 9.10.1 Joints and joining methods: A-53

10. CERAMIC MATERIALS

- 10.11 Fatigue properties of materials (data-generating studies): A-138
- #### 11. CEMENT, MORTAR, CONCRETE
- 11.1 Basic research, nature of fatigue:
 - 11.1.5 Deformation and fracture mechanisms: E-79
 - 11.2 Composition and processing variables:
 - 11.2.1 Composition:
 - 11.2.1.3 Reinforcing, laminating or filler materials: A-18, A-161
 - 11.7 Fatigue damage and measurement:
 - 11.7.1 Detection of damage:
 - 11.7.1.2 After cracking: A-18
 - 11.7.3 Cumulative damage:
 - 11.7.3.1 Prior stress or strain history: A-162
 - 11.9 Engineering problems and design:
 - 11.9.2 Empirical reduction of fatigue information to formulas: A-162
 - 11.9.4 Stress-range diagrams: A-161, A-162
 - 11.11 Fatigue properties of materials (data-generating studies): A-162, B-44
 - 11.12 Theoretical discussions, general reviews: B-44
 - 11.12.1 Theoretical treatments, fatigue and related effects: A-161

12. JOINTS AND JOINING METHODS

- 12.2 Composition and processing variables:
 - 12.2.5 Defects: E-112
 - 12.2.6 Heat treatment (excluding surface hardening): E-3
- 12.3 Geometric factors:
 - 12.3.2 Shape: C-4
 - 12.3.4 Stress concentrations: C-15, E-3, E-87, E-112
- 12.4 Surface factors:
 - 12.4.7 Residual stresses: C-4

- 12.5 Other influencing variables:
 - 12.5.2 Mean stress, alternating stress: E-112
- 12.7 Fatigue damage and measurement:
 - 12.7.1 Detection of damage:
 - 12.7.1.2 After cracking: E-87
 - 12.7.3 Cumulative damage:
 - 12.7.3.5 Step, sequential, spectrum tests: C-15
- 12.9 Engineering problems and design: C-4
 - 12.9.2 Empirical reduction of fatigue information to formulas: E-87
 - 12.9.3 Application of fatigue data in design: C-15
- 12.10 Fatigue properties of structures and machines:
 - 12.10.1 Joints and joining methods:
 - 12.10.1.1 Rivets and riveted joints: E-31
 - 12.10.1.2 Bolts and bolted joints: A-180, C-4
 - 12.10.1.3 Spot welds and other fusion welded joints: C-15, E-87, E-88
 - 12.10.1.4 Adhesives and adhesive joints: C-25, E-68
 - 12.10.3 Large scale structural and machine members: E-87
- 12.11 Fatigue properties of materials (data-generating studies): C-25

13. OTHER NONMETALLIC MATERIALS

- 13.1 Basic research, nature of fatigue:
 - 13.1.4 Correlations, mechanical properties:
 - 13.1.4.1 Anelasticity: A-125
 - 13.1.5 Deformation and fracture mechanisms: E-92
- 13.2 Composition and processing variables:
 - 13.2.7 Other factors: D-4
- 13.3 Geometric factors:
 - 13.3.2 Shape: E-92
 - 13.3.4 Stress concentrations: A-187
- 13.5 Other influencing variables:
 - 13.5.1 Speed: E-92
 - 13.5.4 Type of loading: E-92
- 13.6 Environmental factors:
 - 13.6.1 Temperature: A-125
 - 13.6.1.1 High: E-92
 - 13.6.5 Thermal cycling, strain cycling, low cycle fatigue: E-92
- 13.7 Fatigue damage and measurement: E-92
- 13.9 Engineering problems and design:
 - 13.9.2 Empirical reduction of fatigue information to formulas: E-92
 - 13.9.3 Application of fatigue data in design: E-92
- 13.11 Fatigue properties of materials (data-generating studies): E-26, E-108
- 13.12 Theoretical discussions, general reviews: E-92