

Table of Contents

1 Introduction

- 1.1 History
- 1.2 ASTM D11 Standards
- 1.3 Purpose
- 1.4 Economic Savings for Users and Producers Through Test Method Rationalization
- 1.5 Importance of Quality
- 1.6 Standard Target Values and “Tolerance Stack-up”
- 1.7 Testing Bias
- 1.8 What Makes for a Good Standard Test Method?
 - 1.8.1 Accuracy
 - 1.8.2 Repeatability
 - 1.8.3 Reproducibility
 - 1.8.4 Stability
 - 1.8.5 Linearity
- 1.9 The Rubber Process
- 1.10 Raw Rubber and Compounding Ingredients
- 1.11 The Recipe

2 General Test Methods

- 2.1 Introduction to the Rubber Test Laboratory
 - 2.1.1 Compounding ingredient storage system
 - 2.1.2 Weighing systems
 - 2.1.3 Mixer Systems procedure
- 2.2 General Methods
 - 2.2.1 Mooney Viscometer ASTM D1646
 - 2.2.1.1 Mooney viscosity
 - 2.2.1.2 Mooney Stress Relaxation Test
 - 2.2.1.3 Measuring Pre-Vulcanization Characteristics
 - 2.2.2 Oscillating Disk Curemeter ASTM D2084
 - 2.2.2.1 – ODR Cure Test Parameters
 - 2.2.3 Rotorless Curemeter ASTM D5289
 - 2.2.4 Rotorless Shear Rheometer ASTM D6204
 - 2.2.4.1 Elastic Torque (S')
 - 2.2.4.2 Viscous Torque (S'')
 - 2.2.4.3 tangent δ (delta)
 - 2.2.4.4 Storage (Elastic) Modulus (G')
 - 2.2.4.5 Loss (viscous) Modulus (G'')
 - 2.2.4.6 Dynamic Viscosity η' η'' η^*
 - 2.2.5 Tensile Properties ASTM D412
 - 2.2.6 After-cure Dynamic Properties for Quality Assurance and Development ASTM D6601
 - 2.2.7 Other Cured Physical Property Measurements

- 2.2.7.1 Tear resistance ASTM D 624
- 2.2.7.2 Air Oven Aging ASTM D573
- 2.2.7.3 Goodrich Flexometer Heat Buildup ASTM D623
- 2.2.7.3 Flex Cracking Resistance
- 2.2.7.4 Liquid Immersion Properties ASTM D 471
- 2.2.7.5 Compression Set ASTM D 395
- 2.2.7.6 Rubber Hardness ASTM D 2240
- 2.2.7.7 Abrasion Resistance ASTM D 2228
- 2.2.7.8 Low Temperature Properties ASTM D 1053
- 2.2.7.8 Ozone Resistance D1171
- 2.2.8 The Standard Classification System for Rubber Products used in Automotive Applications ASTM D2000

3 Testing Natural Rubber

- 3.1 Introduction and history
- 3.2 Sampling and sample preparation by ASTM D1485
- 3.3 Technical grades and basis for classification by ASTM D 2227
- 3.4 Methods for Chemical Analysis of Natural Rubber by ASTM D1278
 - 3.4.1 Percent Dirt
 - 3.4.2 Volatile Matter
 - 3.4.3 Copper Content
 - 3.4.4 Manganese Content
 - 3.4.5 % Ash
 - 3.4.6 Iron Content
 - 3.4.7 Acetone Extract
 - 3.4.8 Nitrogen
- 3.5 Plasticity Retention Index, ASTM D3194-99
- 3.6 Color Index ASTM D3157
- 3.7 Standard Test Method for Evaluation of Natural Rubber ASTM D3184
- 3.8 New Standard Test Method for Characterizing Natural Rubber Grades – ASTM D6204, Part B

4 Testing Synthetic Rubber

- 4.1 Synthetic Rubber History and Nomenclature
- 4.2 Consumer-Producer Agreement
- 4.3 Physical Tests for Synthetic Rubber
- 4.4 Standard Test Recipes and Test Procedures
- 4.5 Processability of SBR with the Mooney Viscometer
- 4.6 Chemical Tests for Synthetic Rubbers
 - 4.6.1 Organic Acids, Soap, Oil, Total Extractables
 - 4.6.1.1 Total Extractables
 - 4.6.1.2 Organic Acid and Soap
 - 4.6.1.3 Oil
 - 4.6.2 Volatile Matter
 - 4.6.3 Total and Water Soluble Ash
 - 4.6.4 Determination of Carbon Black in Masterbatch

- 4.6.5 Percent Gel, Swelling Index, and Dilute Solution Viscosity
- 4.6.6 Nitrogen Content of NBR (or HNBR)
- 4.6.7 Test Methods for HNBR
 - 4.6.7.1 Unsaturation of HNBR by Iodine Value
 - 4.6.7.2 Unsaturation of HNBR by Infrared Spectrophotometry
- 4.6.8 EPDM Tests
 - 4.6.8.1 Percent ENB or DCPD in EPDM terpolymers
- 4.6.9 SBR Tests
 - 4.6.9.1 Bound Styrene in SBR
- 4.6.10 Testss for CIIR or BIIR
 - 4.6.10.1 Determination of Bromine in the Presence of Chlorine by Oxygen Combustion
- 4.6.11 General Comment on Determination of Metals in Polymers

5 Testing Carbon Black

- 5.1 Introduction
 - 5.1.1 How is Carbon Black Used?
 - 5.1.2 What are Surface Area, Structure and Surface Activity – Why are they important
- 5.2 Classification
 - 5.2.1 Basis for Classification (D 1765)
- 5.3 Standard Reference Blacks
 - 5.3.1 Validation of Test Method Precision and Bias (D 4821)
 - 5.3.2 Improving Test Reproducibility Using ASTM Reference Blacks (D 3324)
- 5.4 Tests which Relate to Surface Area (Particle Size)
 - 5.4.1 Iodine Adsorption Number (D 1510)
 - 5.4.2 Nitrogen Adsorption
 - 5.4.3 CTAB (Cetyltrimethyammonium Bromide) Surface Area (D 3765)
 - 5.4.4 Primary Aggregate Dimensions from Electron Microscope Image Analysis (D 3849)
- 5.5 Tests which Relate to Structure (Aggregates and Agglomerates)
 - 5.5.1 Oil Absorption Number (D 2414)
 - 5.5.2 Oil Absorption Number of Compressed Sample (D 3493)
 - 5.5.3 Compressed Volume Index (D 6086)
- 5.6 Pellet Quality
 - 5.6.1 Pour Density (D 1513)
 - 5.6.2 Pellet Size Distribution (D 1511)
 - 5.6.3 Pelleted Fines and Attrition (D 1508)
 - 5.6.4 Sieve Residue (D 1514)
 - 5.6.5 Individual Pellet Hardness
 - 5.6.5.1 Individual Pellet Hardness (D 3313)
 - 5.6.5.2 Automated Individual Pellet Hardness (D 5239)
 - 5.6.5.3 Mass Strength (D 1937)
- 5.7 Rubber Test Recipes and Properties

5.7.1 Carbon Black in Styrene-Butadiene Rubber – Recipe and Evaluation Procedure (D 3191) and Carbon Black Evaluation in Natural Rubber (D 3192)

6 Testing Silica and Organosilanes

6.1 Introduction

6.2 Silica Types

6.2.1 Silica Applications versus Carbon Black

6.2.2 Classification

6.3 Surface Area

6.3.1 Surface Area by BET Nitrogen Adsorption

6.3.1.1 Surface Area by Single Point B.E.T. Nitrogen Adsorption (D5604)

6.3.1.2 Surface Area by Multipoint B.E.T. Nitrogen Adsorption (D1993)

6.3.2 Surface Area by CTAB (Cetyltrimethylammonium Bromide)

6.3.2.1 CTAB (Cetyltrimethylammonium Bromide) Surface Area (NEW)

6.4 Structure (Aggregates and Agglomerates)

6.4.1 n-Dibutyl Phthalate Absorption Number (New)

6.5 General Methods

6.5.1 Volatiles (D6738)

6.5.2 pH Value (D6739)

6.6 Organosilanes

6.6.1 Determination of Residue on Ignition (D6740)

6.6.2 Determination of Sulfur in Silanes (D6741)

6.6.3 Silanes used in Rubber Formulations (bis-(triethoxysilylpropyl)sulfanes): Characterization by High Performance Liquid Chromatography – (New)

6.6.4 Silanes used in Rubber Formulations (bis-(triethoxysilylpropyl)sulfanes): Characterization by Gas Chromatography (New)

7 Testing Mineral Fillers for Use in Rubber

7.1 Ground Coal

7.1.1 Particle Size

7.1.2 Sieve Testing

7.1.3 Ash

7.1.4 Alpha Quartz

7.1.5 Heat Loss (moisture)

7.1.6 Acidity

7.1.7 Volatile Matter

7.1.8 Density

7.2 Titanium Dioxide

7.2.1 Titanium Dioxide Purity

7.2.2 pH Measurements

- 7.2.3 Coarse Particles
- 7.2.4 Moisture Content
- 7.2.5 Rutile Content
- 7.2.6 Tint Strength and Brightness
- 7.3 Clay
- 7.4 Natural Calcium Carbonate
- 8 Oils, Plasticizers and Other Rubber Chemicals
 - 8.1 Rubber Processing and Extender Oils
 - 8.1.1 Aromaticity
 - 8.1.2 Average Molecular Weight
 - 8.1.3 Volatility
 - 8.1.4 Polar Compounds
 - 8.1.5 Asphaltenes
 - 8.1.6 Wax content
 - 8.1.7 ASTM Oil Classification
 - 8.1.8 ASTM Oil Tests
 - 8.1.8.1 Clay-Gel Analysis, A Column Chromatographic Method (D2007)
 - 8.1.8.2 Viscosity-Gravity Constant (D2501)
 - 8.1.8.3 Kinematic Viscosity (D445)
 - 8.1.8.4 Aniline Point. and Mixed Aniline Point (D611)
 - 8.1.8.5 Pour Point (D97)
 - 8.1.8.6 Acid and Base Number by Titration (D974)
 - 8.1.8.7 API Gravity (D1298)
 - 8.1.8.8 Color (D1500)
 - 8.1.8.9 UV Absorbance (D2008)
 - 8.1.8.10 Flash Point Open Cup (D92)
 - 8.2 Synthetic Plasticizers
 - 8.2.1 Standard Abbreviations
 - 8.2.2 Standard Test Methods
 - 8.2.2.1 Specific Gravity (D70, D891, and D2111)
 - 8.2.2.2 Color (D1209 and D1544)
 - 8.2.2.3 Refractive Index (D1218)
 - 8.2.2.4 Saponification Value (D1962)
 - 8.2.2.5 Brookfield Viscosity (D2196)
 - 8.2.2.6 Heat Loss (D2288)
 - 8.2.2.7 Karl Fischer (E203)
 - 8.2.2.8 Flash Point Open Cup (D92)
 - 8.3 Curatives
 - 8.3.1 Sulfur
 - 8.3.1.1 Sulfur Insolubles (D4578)
 - 8.3.1.2 Percent Oil (D4573)
 - 8.3.1.3 Acidity (D4569)
 - 8.3.1.4 Wet Sieve (D4572)
 - 8.3.1.5 Percent Ash (D4574)

8.3.2 Rubber Accelerators

- 8.3.2.1 Standard Abbreviations
- 8.3.2.2 Initial Melting Point (D1519)
- 8.3.2.3 Wet Sieve (Similar to D4572)
- 8.3.2.4 Percent Ash (D4574)
- 8.3.2.5 Percent Heat Loss (D4571)
- 8.3.2.6 Percent Moisture in Sulfenamides (D4818)
- 8.3.2.7 Percent Insolubles in Sulfenamides (D4934)
- 8.3.2.8 Assay for Sulfenamides (D4936)
- 8.3.2.9 MBTS Assay (D5051)
- 8.3.2.10 Assay for DPG & DOTG (D5054)
- 8.3.2.11 MBT Assay (D1991)

8.3.3 Zinc Oxide

- 8.3.3.1 American Process or Direct Type
- 8.3.3.2 French Process or Indirect Type
- 8.3.3.3 Secondary Zinc Oxide – Chemical Type
- 8.3.3.4 Secondary Zinc Oxide - Metallurgical
- 8.3.3.5 – Zinc Oxide Treatment
- 8.3.3.6 Zinc Oxide Test Methods
 - 8.3.3.6.1 Surface Area (D3037 and D4315)
 - 8.3.3.6.2 Percent Lead and Cadmium (D4075 and D4315)
 - 8.3.3.6.3 Percent Residue on 45 μ m Sieve (D4315)
 - 8.3.3.6.4 Percent Heat Loss at 105°C (D280)
 - 8.3.3.6.5 Percent Sulfur (D3280 and D4315)
 - 8.3.3.6.6 Percent Zinc Oxide Purity (D3280 and D4315)
 - 8.3.3.6.7 Test Recipe (D4620)

8.3.4 Stearic Acid

- 8.3.4.1 Iodine Value (D1959)
- 8.3.4.2 Titer (D1982)
- 8.3.4.3 Acid Value (D1980)
- 8.3.4.4 Saponification Value (D1962)
- 8.3.4.6 Unsaponification Matter (D1965)
- 8.3.4.7 Trace Metal (D4075)

8.4 Antidegradants

8.4.1 Class I: p-Phenylenediamine (PPDs)

- 8.4.1.1 Type 1: N,N'-dialkyl-p-phenylenediamines
- 8.4.1.2 Type II: N-alkyl-N'aryl-p-phenylenediamines
- 8.4.1.3 Type III: N, N'-diaryl-p-phenylenediamines

8.4.2 Trimethyl-dihydroquinolines (TMQs)

8.4.3 Class 3, Phenolics

- 8.4.3.1 Type I: Monofunctional phenols
- 8.4.3.2 Type II: Bifunctional phenols
- 8.4.3.3 Type III: Multifunctional Phenols

8.4.4 Class 4, Alkylated Diphenylamines

8.4.5 Class 5, Aromatic Phosphites

8.4.6 Class 6, Diphenylamine-Ketone Condensates

8.4.7 Standard Abbreviations

8.4.8 Test Methods for Antidegradants

8.4.8.1 Purity of p-Phenylenediamine Antidegradant by Gas Chromatography (D4937)

8.4.8.2 Purity of Phenolic Antioxidants

8.4.8.3 Purity of TMQs, Alkylated Diphenylamines and Phosphite Antidegradants

8.4.8.4 Volatile Materials for PPDs

8.4.8.5 Percent Ash

8.4.8.6 Softening Point

8.4.8.7 Hydrolysis Stability

8.5 Protective Waxes

8.5.1 Test Methods

8.5.1.1 Boiling Point, Determination by GC Distillation (D2887)

8.5.1.2 Melting Point and/or congealing point (D87, D938, D3944, D4419)

8.5.1.3 Refractive Index (D1747)

8.5.1.4 Percent Oil (D721)

8.5.1.5 Viscosity (D445)

8.5.1.6 Color (D1500)

8.5.1.7 Needle Penetration (D1321)

9 Testing Recycled Rubber

9.1 Definition and rubber recycling processes

9.1.1 Reclaiming

9.1.2 Ground Rubber

9.1.3 Cryogenic Ground Rubber

9.1.4 Wet Ground Rubber

9.1.5 "Devulcanization" Process

9.1.6 Need For Standards

9.2 Storage, QA Sampling and Test Plans

9.2.1 Material and Safety Data Sheets (MSDS)

9.2.2 Crumb Rubber Storage

9.2.3 Sampling & Test Plans

9.3 Test Methods

9.3.1 Particle Size (PS) and Particle Size Distribution (PSD)

9.3.2 Particle Size Classification (ASTM D 5603-01)

9.3.3 Chemical Analysis (ASTM D 5603-01)

9.3.3.1 Percent Extractables (ASTM D 297, Section 19)

9.3.3.2 Percent Ash (ASTM D 297, Section 35)

9.3.3.3 Percent Carbon Black (ASTM D 297, Section 39)

9.3.3.4 Percent Moisture Content (ASTM D 1509-2000) or Heating Loss

9.3.3.5 Percent Natural Rubber Content (ASTM D 297, Section 53)

9.3.3.6 Percent Rubber Hydrocarbon (ASTM D 297

9.3.3.7 Iron and Fiber Content (ASTM D 5603-01, Section 7)

9.4 Evaluation of Recycled Rubber in Compounds

10 Standard Test Methods – Insuring High Quality Output

10.1 Introduction

10.2 Part 1 : Fundamentals of Testing Operations

10.2.1 Step 1. Planning

10.2.2 Step 2. Measurement Methodology : Selecting Test Methods

10.2.2.1 Precision

10.2.2.2 Sensitivity

10.2.2.3 Calibration

10.2.2.4 Traceability

10.2.3 Step3. Basic Sampling Principles

10.2.3.1 Sampling

10.2.3.2 Intuitive Sampling

10.2.3.3 Statistical Sampling

10.2.3.4 Protocol Sampling

10.2.4 Step 4. Measurement, Data Reporting and Analysis

10.2.4.1 Reference Materials : D4678 and D5900

10.2.4.2 Reference Materials : D3324, D4122

10.3 Part 2 : Testing - Using Specific Standards

10.3.1 Natural and Synthetic Rubber, Carbon Black

10.3.2 Process Performance and Capability Indexes

10.4 Part 3 : Recent Developments in Test Method Technical Merit

10.4.1 Test Method Precision : D4483

10.4.1.1 Background

10.4.1.2 Outlier Detection

10.4.1.3 Outlier Rejection

10.4.1.4 Outlier Deletion or Replacement

10.4.2 Test Sensitivity : D6600

10.4.2.1 Background

10.4.2.2 The Measurement Process

10.4.2.3 Test Sensitivity Concepts