Index

A

Abrasion tests, 10, 77-85, 93 Armstrong abrasion, 95, 97, 98 Mar resistance, 78, 117 Performance predictions (see Physical testing) Soft-hair wheelbrush, 79-80, 117 Spherical stylus scratch, 79, 85 Taber abrasion, 79 Abrasive wear (see Wear mechanisms) ANSI test procedures, 80, 82, 85

B

Boundary conditions, 1, 7, 9, 10, 11, 13, 59, 114, 116, 118 Definition, 6 Geometry, 21, 95 Thickness, 7, 9, 59, 72–73, 76, 107–108, 117 Topography, 92, 93, 94, 98

С

Chemical wear (*see* Wear mechanisms) Component tests Definition, 8, 114 Examples, 11, 29–30, 57–58, 70, 72, 104, 106 Creep, 12, 110, 112

D

Data presentation, 13, 108, 118

Typical property tables, 1, 13, 102, 103, 105, 111, 113, 114 Deformation wear (see Wear mechanisms) Design requirements, 1, 103, 105, 110, 112, 117 Design technology, 109, 110, 111, 118 Role of ASTM, 112–113, 119 Ductile-brittle transitions, 22–29, 60, 64–70, 74, 116

E

Environments Effects of, 1, 3, 5, 7, 12, 16, 59, 63, 64–70, 76, 92, 95, 105, 114 Inclusion in material evaluation, 13, 103, 104, 117, 118 Excitation functions (*see* Input/ output functions)

F

Fabrication influences, 4, 7, 19, 22-29, 56, 59, 70-72, 102, 104, 105, 117 Fatigue testing, 32-44, 115 Cyclic, 32, 35, 36 Performance predictions (see Physical testing) Static, 32, 35, 38 Prot method, 41, 42, 43 Fatigue wear (see Wear mechanisms)

FDA, 103

Fracture toughness, 16, 19–20, 30 Crack opening displacement, 17, 18, 19, 20, 21 Experimental methods, 16-17, 114, 115 Performance predictions (see Physical testing) Stress intensity factor, 17, 21 Validity conditions, 18, 20, 30 Friction testing, 80-85 Paper clip friction test, 84, 85, 87, 88, 89, 90, 117 Performance prediction (see Physical testing) Point contact friction test, 81-83, 84, 88, 117 Sled friction test, 80, 84, 85, 117 Fundamental tests Definition, 7, 114 Examples, 8, 10-11, 16, 41, 115, 118

Performance predictions (see Physical testing) Special impact tests, 107 Input/output functions, 1, 6-7, 11, 13, 92, 98, 114, 118 Shape and amplitude, 6, 115, 119 Interfacial wear (see Wear mechanisms)

L

Load-deformation curves, 19-20, 47-49, 51-52, 54-56, 62-63

M

Material evaluation guidelines General evaluation, 13 Known application, 12–13 Mechanical spectrometry, 7, 118, 119 Microprocessors, 119

0

Optical haze Light transmission, 103 Measurement of abrasion, 78, 79, 80, 81

P

Performance requirements (see Design requirements) Physical testing Correlation with end-use performance, 1, 4, 12–13, 29–30, 35, 43, 44, 50–53, 57–58, 78, 80, 81, 83–85, 88, 90, 91, 92, 95–96, 98–99, 104, 105–107, 114, 115, 116, 117, 118, 119 Definition of, 6–7, 114 Nonstandard methods Assessment, 79, 81, 84–85, 88, 107 Rationale, 3, 119

Η

Heat resistance (see Environments) Hybrid tests Comparison with practical tests, 10 Definition, 9–10, 114 Examples, 10, 11, 13, 78, 79, 117, 118

I

Impact testing Charpy, 46, 51, 57, 116 Falling weight, 53, 56, 57, 60, 61 Gardner, 61, 116 Instrumented, 46, 116 Advantages, 45–46, 54 Applications, 49, 53 Incipient damage, 52–53, 116 Instrumentation, 46–49, 60–61 Izod, 7, 9, 10, 11, 12, 46, 57, 116

Reasons for testing, 3–4, 77 Relevancy, 12, 77, 78, 85, 88, 91, 114, 115, 119 Standard methods Assessment, 11-12, 30, 35, 53, 55, 60, 77-79, 80, 84, 90, 95, 98-99, 103-104, 107, 108, 111, 112, 115, 118 Comparison, 8-11 Types of methods, 7-10, 45, 114 Practical tests Definition, 9, 114 Examples, 9, 11, 36, 45, 79, 81, 88, 98, 99, 107-108, 117 Processing (see Fabrication influences)

T

Temperature (see Environment) Temperature measurement, 61 Time Effects of, 1, 3, 6 Inclusion in material evaluation, 13, 103 Long-term strength, 41, 44, 115-116

U

Underwriters Laboratories, 105, 107

V

Viscoelasticity 6, 110–111, 119 Strength of materials, 110 Stress-strain properties, 110

W

Wear Mechanisms, 91, 92, 93, 94, 95, 98-99, 118 Performance predictions (see Physical testing) PV factor, 96, 97, 98, 118 Specific wear rate, 96 Thrust-washer tester, 96 Wear testing, 91, 92, 95-97, 117 Wohler method, 41

R

Rate effects, 21-22, 97, 98 Response functions (see Input/ output functions)

S

Scratch tests (see Abrasion tests) Stress analysis, 111 Stress rupture (see Fatigue, static) Systems analysis (see Input/output functions)