

STP1549

Building Walls Subject to Water Intrusion and Accumulation: Lessons from the Past and Recommendations for the Future

Table of Contents

Overview

The High Costs of Minimum Quality Cement Plaster (Stucco) Assemblies: A Performance Case Study from California — *P. Vora and J. A. Bowsby*

Evaluation of the Potential for Corrosion, Mold Growth, and Moisture Accumulation within Typical Brick Veneer Wall Assemblies Designed per 2006 International Energy Code in a Mixed Humid Climate — *C. M. Wagner, R. A. Cyphers, and R. A. Whitlock*

Utilizing a Modified AAMA 501.1 Dynamic Wind Generation to Simulate Wind-Driven Rain in Windows, Curtain Walls, Architectural Metal Walls, Masonry, EIFS, and Concrete Facades — *M. T. Williams and Jasha Kistler*

Value Analysis of Building Enclosure Systems—Problems and Solutions — *J. E. Peterson, R. A. Cyphers, and W. R. Nash*

Using Hygrothermal Simulation to Assess Risk of Water Accumulation from Wall Assembly Defects — *T. A. Weston*

Water Leakage Testing of Glass and Metal Curtain Walls — *S. G. Naggatz and S. F. Sinusas*

Flood Damage-Resistant Materials: Research and Evaluation — *J. Nieves, J. Moline, M. House, R. Walker, and J. Ingargiola*

Comparative Analysis of Fluid-Applied Air Barrier Products — *K. S. Wissink, L. K. Bashaw, and S. S. Ruggiero*

Dimensional Stability Considerations in Spray Polyurethane Foam Air Barriers — *A. W. Wagner, and J. E. Peterson*

Stone Cladding Joint Treatment Conundrum: Sealant or Mortar — *E. Cardini, R. Kwon, and E. Gerns*

Applying a Methodology of Investigation Tailored to the Building Envelope Affected by Water Infiltration — *J. Borsellino and R. Trempe*

Case Study Repair of Shadow Box Spandrel Condensation — *B. S. Kaskel and C. M. Ceja*

The Richmond Civic Center Complex: How Building Rehabilitation Can Help Save the World by Reducing Costs, Waste and Preserving Our Past — *J. E. Mendygral and C. L. Searls*

Design Requirements for Building Envelopes to Minimize Water Runoff — *P. Fazio*