BUHLDING FACADE MAINTENANCE, REPAIR, and INSPECTION

STP 1444

Editors: Jeffrey L. Erdly and Thomas A. Schwartz



STP 1444

Building Façade Maintenance, Repair, and Inspection

Jeffrey L. Erdly and Thomas A. Schwartz, editors

ASTM Stock Number: STP1444



ASTM International 100 Barr Harbor Drive PO Box C700 West Conshohocken, PA 19428-2959

Printed in the U.S.A.

Copyright © 2004 ASTM International, West Conshohocken, PA. All rights reserved. This material may not be reproduced or copied, in whole or in part, in any printed, mechanical, electronic, film, or other distribution and storage media, without the written consent of the publisher.

Photocopy Rights

Authorization to photocopy items for internal, personal, or educational classroom use, or the internal, personal, or educational classroom use of specific clients, is granted by ASTM International (ASTM) provided that the appropriate fee is paid to the Copyright Clearance Center, 222 Rosewood Drive, Danvers, MA 01923; Tel: 978-750-8400; online: http://www.copyright.com/.

Peer Review Policy

Each paper published in this volume was evaluated by two peer reviewers and at least one editor. The authors addressed all of the reviewers' comments to the satisfaction of both the technical editor(s) and the ASTM International Committee on Publications.

To make technical information available as quickly as possible, the peer-reviewed papers in this publication were prepared "camera-ready" as submitted by the authors.

The quality of the papers in this publication reflects not only the obvious efforts of the authors and the technical editor(s), but also the work of the peer reviewers. In keeping with long-standing publication practices, ASTM International maintains the anonymity of the peer reviewers. The ASTM International Committee on Publications acknowledges with appreciation their dedication and contribution of time and effort on behalf of ASTM International.

Foreword

The Symposium on *Building Façade Maintenance, Repair, and Inspection* was held in Norfolk, VA on October 12–13, 2002. ASTM International Committee E06 on Performance of Buildings served as its sponsor. Symposium chairmen and co-editors of this publication were Jeffrey L. Erdly and Thomas A. Schwartz.

Contents

| Foreword | iii |
|---|-----|
| Overview | vii |
| SECTION I: Purpose and Background to Façade Ordinances | |
| Reporting Unsafe Conditions at Public Schools and Private Structures— JEFFREY L. ERDLY AND GREGG M. BEKELJA | 3 |
| Evolution of the Development of the Chicago Façade Inspection Ordinance — IAN R. CHIN AND HOLLY GERBERDING | 9 |
| New York City's Local Law 10 at Twenty: Critical Issues for the Critical Examinations—DAVID MAY | 30 |
| SECTION II: Addressing Historic Buildings | |
| Façade Ordinances and Historic Structures—Theoretical and Practical Conservation Issues in Inspection and RepairKECIA L. FONG AND CECE LOIUE | 47 |
| New Methods for Designing Restoration Repairs for Historic Building Façades: A Case Study—MICHAEL J. SCHEFFLER AND KENNETH M. ITLE | 65 |
| Terra Cotta FaçadesKURT R. HOIGARD, GEORGE R. MULHOLLAND, AND ROBERT C. HAUKOHL | 75 |
| Emergency Repairs for Historic Façades—DOREEN PULLEY AND ELWIN C. ROBISON | 91 |
| SECTION III: Investigation and Data Collection Techniques | |
| Façade Maintenance: Owner's Techniques for Data Management—JOSEPH J. CHADWICK AND JOYCE T. MCJUNKIN | 109 |
| Industrial Rope Access—An Alternative Means for Inspection, Maintenance, and Repair of Building Facades and Structures— | |
| HAMID VOSSOUGHI AND REHAN I. SIDDIQUI | 116 |

vi CONTENTS

| Direct Digital Input of Façade Survey Data Using Handheld Computing Devices- | |
|--|-----|
| KENT DIEBOLT, JAMES BANTA, AND CHARLES CORBIN | 124 |
| Seeing and Photographing Your Visual ObservationsMICHAEL A. PETERMANN | 138 |
| Integrating Advance Evaluation Techniques with Terra Cotta Examinations | 149 |
| Unique Considerations for Stone Façade Inspection and Assessment MATTHEW C. FARMER | 162 |
| SECTION IV: MATERIAL AND REPAIR TECHNIQUES | |
| Façade Inspections a Must for Both New and Old Buildings—A Case Study on Two High Rise Structures—W. MARK MCGINLEY AND CHARLES L. ERNEST | 179 |
| How Deteriorated Can Marble Façades Get? Investigation and Design of Repairs — BENJAMIN LAVON | 194 |
| Stone Façade Inspection of 1776 F Street—TIMOTHY TAYLOR AND FREDERICK M. HUESTON | 205 |
| Façade Repair Examples in the Midwest: Cracking, Twisting, and Falling— JAMES C. LABELLE | 215 |
| Glass Façade Assessment—THOMAS A. SCHWARTZ | 230 |
| Concrete Façades: Investigation and Repair Project Approaches —GEORGE I. TAYLOR AND PAUL E. GAUDETTE | 246 |
| Façade Ordinances and Temporary Stabilization Techniques for Historic Masonry Facades—BRENT GABBY AND HAMID VOUSSOUGHI | 260 |
| Designer-Led Design/Build—Alternative Project Delivery Method for Façade Evaluation and Repair Projects—Case Study on and 11 Story Apartment Building—DAVID VANOCKER | 274 |
| SECTION V: MISCELLANEOUS | |
| Preparation For and Collection of Façade Deficiences at Large Complexes— ANDREW P. MADDEN AND MICHAEL A. PETERMANN | 293 |
| Guidelines for Inspection of Natural Stone Building Façades—AMY PEEVEY BROM | 301 |
| Assessing the Apparent Watertight Integrity of Building Façades—DOUGLAS R. STIEVE, ALICIA E. DIAZ DE LEON, AND MICHAEL J. DRERUP | 316 |
| Indexes | 324 |

Overview

Building facades are not static. They move in response to wind effects and temperature changes. They interact with the structural frames that support them. They degrade with age and, occassionally, lose attachment to the building. Loss of façade materials is a growing problem. Only eight U.S. cities have adopted some form of local ordinance requiring inspection of building facades to detect unsafe conditions, and these ordinances vary considerably in thoroughness, effectiveness, and enforcement. In some cases, façade ordinances have done little to reduce the threat and, in fact, have resulted in a false sense of security concerning the safety of building facades. Facades that have been inspected have lost significant façade materials within a year or two of the inspection.

The papers published in this special technical publication (STP) were presented at a symposium entitled *Building Façade Maintenance, Repair and Inspection,* held in Norfolk, Virginia on October 12–13, 2002. ASTM International Committee E06 on performance of buildings sponsored the symposium as a parallel effort with the final development of ASTM's Standard E 2270, "Standard Practice for Periodic Inspection of Building Facades for Unsafe Conditions," which received final approval in the spring of 2003.

The first known building code, Hammurabi's Code of Laws (1700 B.C.), included the following: "if a builder build a house for someone and does not construct it properly and the house which he build fall in and kill it's owner, then that builder shall be put to death." While the sentence of death seems harsh, the underlying implication of a responsibility to protect those using our buildings during their everyday life is clear. It is the intent of the papers in this book, combined with ASTM Standard E 2270, to provide a rational guide for building owners and governing authorities to help ensure the safety of our aging building infrastructure.

The papers contained in this publication provide insight with regard to four major headings. They include: 1) Purpose and Background to Façade Ordinances; 2) Addressing Historic Buildings; 3) Investigation and Data Collectino Techniques; and 4) Material and Repair Techniques. The authors who generated these papers, architects, Engineers, public and private institutional facility owners, and contractors, bring to their work first hand knowledge and experience that covers the wide diversity of architecture within North America.

These papers, combined with ASTM Standard E 2270, represent a starting point for this important work. ASTM committee E06.55, through its ongoing task group, will be expanding its work to include additional annex information. The proposed topics include, but are not limited to, public sidewalk protection, safety of inspections, hazardous materials, safety considerations for inspection openings, mechanisms of distress, structural movement, and material-specific guidelines.

> Jeffrey L. Erdley Masonry Preservation Systems, Inc. Bloomsburg, PA

Thomas A. Schwartz Simpson Gumpertz & Heger, Inc. Waltham, MA

ISBN # 0-8031-3475 Stock #:1STP1444

THE OWNER.

www.astm.org