

# Subject Index

## A

- Abrasive cleaning, 31, 38–41, 53, 66
  - compared with water washing, photograph, 45
  - of masonry, 99–100
- Acidic cleaners, 41–42
- Aerosol paints, 14
- Alkaline cleaners, 42
- Aluminum siding, testing for graffiti removal, 15
- Architectural cleaning, 57, 74, 77
- Architectural preservation, 71, 77
- ASTM standards
  - C 67-83: 17
  - C 88-83: 4
  - D 1310-82: 18
- Atmospheric pollutants, 108

## B

- Bricks, graffiti removal from, 25, 74
  - effectiveness, 20, 21
  - table, 21
  - specifications for, appendix, 79
  - testing for graffiti removal, 15
  - table, 17
- Bricks, water-soluble salts in, 3
- Building cleaning, 83, 96
- Building maintenance guidelines, 85
- Building management, public buildings, 85

- Building materials, test substrates, 15
  - table, 17
- Building restoration, 3, 25, 45, 51
  - historic structures, 72

## C

- Chemical cleaning, 31, 54, 62, 66
  - of historic structures, 71–74, 77
  - of masonry, 98
  - specifications, appendix, 78
- Cleaning methods, 53, 57
  - abrasive cleaning, 99
  - chemical cleaning, 98–99
  - precleaning, 59, 62
  - standards, 5
  - water-safe cleaning (WSC), 58–65
  - photographs, 59–65
  - water washing, 98
- Cleaning/renovation programs, 25–26, 58, 97
  - testing, 97–98
- Cleaning specifications, 77
  - appendix, 78
- Cleaning standards, for public buildings, 86
- Coatings, water-repellent, 97, 100
- Color retention test methods for graffiti removal, 17, 19
  - table, 21
- Computer-based energy-dispersive X-ray microanalyzer, 113

- Concrete, water-soluble salts in, 3
- Conservation/stabilization (*see* Marble deterioration)
- Contract performance, for historic preservation, 77
- Crayon marks, tests for removal, 19

## D

- Decay
  - due to sodium sulfate, 4
  - of masonry, causes of, 28
- Desalination, 11, 12
  - Diagrams, 7, 8

## E

- Efflorescences
  - as cause of masonry decay, 3
  - effects of removal after rain, 5
  - removal procedures, 8–9, 11, 12
- Electron microprobe, exploring marble deterioration, 118, 125, 133
- Environmental pollutant data for marble, Schenectady City Hall, 118, 133, 135, 136
- Environmental pollution effects, Schenectady City Hall
  - photographs, 119–124, 126, 127, 139–143, 145, 147, 148
  - photomicrographs, 128–132, 134, 137

## F

- Felt-tip pen, test procedures for removing marks, 19

## G

- German Standard DIN 52111, 4
- Graffiti materials, 15, 17
  - table, 17
- Graffiti removal (*see also* Bricks, graffiti removal from)

- from historic structures, 75
  - specifications for, appendix, 82
- paint removers, effectiveness of, 18–21
  - tables, 18, 21
- test methods, 14, 15
  - for color retention, 17, 19, 21, 22
  - tables, 21, 22
- Granite cleaning
  - historic structures, 74
  - specifications for, appendix, 79
- Gypsum crystals
  - crust removal, 108
  - presence in marble deterioration, 125, 138

## H

- Heterogeneous oxidation, 108
- High-pressure water cleaning, 71
- Historic preservation, 3
  - cleaning, 71, 75, 77, 85
  - specifications for, appendix, 78
  - interior cleaning, public buildings, 86, 87
- Historic structure reports, for public buildings, 87

## I

- Interior cleaning, 85–86, 87
- Ion chromatography, for marble deterioration investigation, 113, 133

## L

- Limestone, cleaning historic structures, specifications for, appendix, 79–80
- Lipstick, tests for removal, 19

## M

- Macrosteriogrammetry, for measuring stone surface erosion, 153, 155
- Macrosteriophotography, 157
- Marble cleaning
  - chemical cleaners, 88
  - conservation/stabilization of Schenectady, New York, City Hall, 110, 146
  - analysis, 113
  - coal fly ash and iron particles, 125
  - extent of deterioration, 135–136
  - gypsum crystals, 125
  - interior marble, 144
  - particulates, 114–117
  - photographs, 109, 119–124, 139–143, 147–148
  - of historic structures
    - specifications for, appendix, 79
- Marble deterioration, 113, 118, 125
- Marking materials, removal from buildings, 21
- Masonry, 3, 14, 52, 83
  - acid-resistant/acid-soluble, 46
  - substrate, 43, 45
  - contaminants, 74
  - surface erosion losses on stone, 153
- Masonry cleaning, 108, 153
  - chemical cleaning, 98
  - of historic structures, 73, 75, 96, 102–103
    - Minneapolis Grain Exchange, 102–103
  - procedures and products, 83
  - standards, 83
  - water washing, 98
- Masonry decay and deterioration, 3, 4–6
  - causes, 28
- Masonry interiors, public buildings, cleaning standards for, 85
- Masonry preservation and restoration, 5

- cleaning, 14, 28, 31, 43, 49–50, 96, 102–104
- cleaning methods, 53, 75–76, 98
- test procedures, 47–48, 98
  - identification of materials, 46
  - identification of stains, 46–47
- Microanalyzer, computer-based
  - energy-dispersive X-ray, in marble cleaning, 113
- Minneapolis Grain Exchange, cleaning experience, 102–103
- Mirabilite ( $\text{Na}_2\text{SO}_4 \cdot 10\text{H}_2\text{O}$ ), role in disintegration of historic structures, 4
- Moisture, as cause of decay, 28
- Monuments, 3
- Mortar repairs, restoration, 108

## O

- Optical microscope, investigation of marble deterioration, 113, 125
- Organic solvent cleaners, 42–43
- Oxidation, sulfur dioxide, cause of marble deterioration, 136

## P

- Paint removal, 75
  - specifications for, on historic structures, appendix, 81–82
  - testing for film removal, 47
- Paint removers, 14, 66
- Pen marks, 14
- Performance criteria, of graffiti paint removers, 19, 20, 21
  - table, 21
- Photogrammetry, 154, 157
- Poultice cleaning, 66
  - marble, 88, 90–91
- Preservation/restoration (*see* Masonry; Historic preservation; Public buildings)
- Pressure washing, 36–38

Public buildings, cleaning interior masonry, 85–86

## R

Renovation programs, 25–26, 58, 97

Restoration mortar repairs, 108

Rock structures, 157

## S

Salts, water-soluble

    crystal concentrations, tables, 10

    desalination removal procedures, 8–9

    effects on masonry, 4

Sandblasting, (*see also* Abrasive cleaning), 66

Sandstone cleaning, of historic structures, 74

    specifications, appendix, 78

Scanning electron microscope, analysis of marble deterioration, 113, 125

Schenectady, New York, City Hall, conservation/restoration of, 107–149

Sodium sulfate, decay due to, 4

Sphinx, 4–6

    table, 6

Stains, surface, identification of, 46–47

Steam cleaning, 31–32, 54

Stereophotography, 154

Stone cleaning, 25, 52, 76, 88–89, 157

Stone durability, 4

Stone surface macrostereogrammetry, for measuring erosion losses, 153

Stress, 4

Suction desalination, 7–8, 11

Sulfuric acid, 108

Sulfur dioxide oxidation, 108

## T

Terra cotta, cleaning of, in historic structures, 74

Therandite ( $\text{Na}_2\text{SO}_4$ ), phase changes into mirabilite ( $\text{Na}_2\text{SO}_4 \cdot 10\text{H}_2\text{O}$ ), cause of disintegration, 4

## W

Water cleaning, 31, 54, 98

    compared with abrasive grit blasting, 45

    pressure, 55, 71

Waterproofing, 99, 100

Water-repellant coatings, 97, 100–101

Water-safe cleaning (WSC) technology (*see* Cleaning methods)

Water soaking, 34–35, 54

Weathering, 3